


Ster-Vis calibration target - 9 x 6 inner corners, 25 mm squares



100 mm - check with a ruler

Print at 100% / Actual size. Measure a square; pass the real size to --square-size.