4



EFR32 Mighty Gecko Sensor Node

5

Selisor Node	
Board Function	Page
Title Page	1
EFR32 RF, Power & IO	2
EFR32 connections & interfaces	3
MEMS Microphone & RGB LEDs	4
SPI & I2C Sensors	5
Debug MCU	6
Debug Misc. & Power	7

Revision History

REVISION HISLOTY	
Rev.	Description
A00	Initial prototypes.
A01	Major update - LED drivers, power topology, component values updated.
A02	Changed buttons, updated component values, removed power switch and added reset button.
	Changed from BMP180 to BMP280. Changed from MPU-9250 to ICM-20648
	Adjusted microphone gain.
в00	Removed the Hall effect sensor
в01	Fixed PCB error that causes the coin cell to short circuit in some cases. Added silk screen text above SW1 and SW2
	· · · · · · · · · · · · · · · · · · ·

SCHEMATIC1



Schematic Title

EFR32 Mighty Gecko Sensor Node

ABS Page Title
Title Page

Document number
BRD4160A

Sheet Created Date
Monday, April 02, 2012

Sheet Medisday, August 24, 2016

Revision
B01

Sheet
Wednesday, August 24, 2016

1 of 7

Design Created Date:
Monday, April 02, 2012











