## Report of Property Loss

Ref#: #SP-90219

Filed: 03/12/2024

Analyst: M. BURNS

Affected Location:

410 South Industrial Way

Ownership information on record includes Evergreen Far ms Ltd.

(primary entity) and maintenance subcontractor Urban Grid Construction.

Damage was reported by the on-site facilities coordinator, who noted structural degradation likely stemming from roof rot compounded by water intrusion.

Please refer to Ever green Farms L T D as the primary account holder for policy #EVG-2024-981.