

# **Lockout card**

## Machine à bloc

Maintenance

Card #:8888

APPROVED BY:

**REVISION DATE:** 

DATE:



# **WORK TO PERFORM** pΙ

MATERIAL REQUIRED		POWER SOURCE		
Boîte de cadenassage (0)		Chimique	Électrique	

#### SWITCH OFF AND LOCKOUT

#	INSTRUCTIONS	DEVICE	ACCESSORY	РНОТО
1	Effectuer l'arrêt de la machine (bouton ou arrêt ou stop)	Bouton		

## **PHOTOS AND LOCATIONS**

#### **WARNINGS:**

All personnel involved must have received lockout training and have all required accessories.

Any work involving installations operating at 50 volts and more must be performed by an electrician. Power must first be measured at ZERO (0) with a meter.

All persons involved in working on the machine must first inform their colleagues and install their own personal lock before making an intervention.

### IF A LOCKOUT IS NOT ADEQUATE, CONTACT YOUR IMMEDIATE SUPERVISOR

### **UNLOCKING AND SWITCHING ON**

#	INSTRUCTIONS	DEVICE	ACCESSORIES	РНОТО				
1	Aviser les personnes concernées et enlever les outils autour de l'équipement							

