

## TECHNICAL CHARACTERISTICS

(CPF002-4)

LAB. TEST FLOOR GRES

07/05/2013

SERIES:	RAIN FOREST	DESCRIP'	TION: SILVER	SILVER	
CODE:	741140	SIZE:	45x90	B50	

Brand:

MARINER

			TESTING METHOD	TECHNICAL DATA	SPECIFICATION REFERENCE EN14411 App. G	LEGEND
*	ISO10545-14		Chromium oxide and iron oxide	5-4	5-4 5 GL: min. 3 5	Classification 5 - stain removal by hot water (55 °C) Classification 4 - stain removal by weak cleaning agent and non-abrasive cloth (ph 7) Classification 3 - stain removal by
*			Solution of Iodine in alcohol	5		
*			Olive Oil	5		
*	FLORIM INTERNAL TEST		Methylene blue	3		
*			Potassium Permanganate	3		abrasive strong cleaning agent (ph 9)  Classification 2 - stain removal by
*			Permanent market	3		strong solvent Classification 1 - stain not removed
*			Shoe Polish	5		Canodifferior 1 - Stain not removed
*		1	Ammonium Chloride 100 g/l	GA		
*	2 Sodium Hypochlorite 20 mg/l		GA	min. B	G = Glazed surface U = Unglazed surface	
*	m	3	HCl 3%	GLA	No requirement, one must indicate the classification.	L = Low concentration H = High concentration A = No sample must show visible signs of chemical attack. B = visible signs of chemical attack
*	45-I	4	Citric Acid100 g/l	GLA		
*	SO 10545-13	5	KOH 30 g/l	GLA		
			HCI 18%		No considerant to	C = Partial or complete loss of the original surface
		7	Lactid Acid 5%		No requirement, to do for intended use in	(V) = Visual classification, as normal
		8	KOH 100 g/l		corrosion risk	classification is not possible
*	DIN 51130 Slip Resistance (R)		13° = R10			
*	*		Abrasion PEI	CLASSE 4	To Declare	
*	B.C.R		Dynamic coefficient of friction	Dry leather: 0,43	Wet rubber: 0,60	
*	ASTM		Static coefficient of friction	Dry: 0,90	Wet: 0,67	
*	ISO 10	Eyes and a	(%) Water Absorption	0,05	≤ 0.5 %	
*			Flexural Strength (N/mm <sup>2</sup> )	51	min. 35	
*	ISO 10545-4		Breaking Stress (N)	3373,1	Sp. ≥ 7.5 min 1.300	Sp. < 7.5 min 700
*			Breaking Load (N)	2599,7	265 KgF	
*			Perception signature shoe	2		1 = Not visible 2 = Visible 3 = Very Visible
*			Cleaning of signature shoe	1		1 = Dry Cleaning
	TEST			2		2 = Wet Cleaning
*			Cleaning of trampling			3 = Failure to clean
						3 = Panture to Clean
*			Perception of dirt after 8/12 h	1		1 = Low 2 = Medium 3 = High
*			Change of the final material compared to the initial	1		1 = Unchanged 2 = Light Change 3 = Strong Change

NOTES:	
Laboratory Technician : Lumetti Barbara	