

Service record: two units ceased at 25.0 months, 3 h 53 min apart; two continue at 26.8 months

