

Acme Robotics -- Support Handbook

This handbook is the source of truth for support policy. Front Desk associates do not have access to this document; the Support Manager tier and above do, via the RAG knowledge base.

Section 1: Returns & Refunds

- Standard return window: 30 days from the delivery date, for all hardware purchased directly from acme.com.
- Acme Pro subscribers (see Section on subscriptions) receive an extended 45-day return window on hardware purchases.
- Returns require an RMA number. Request one by emailing returns@acme.com or through the RMA tool at acme.com/returns.
- Refunds are issued to the original payment method within 5-7 business days of the warehouse receiving the returned item.
- Custom-configured RoboArm X9 units are FINAL SALE once assembled and are not eligible for return.

Section 2: Warranty Coverage

- All Acme Robotics hardware ships with a 2-year limited warranty covering manufacturing defects.
- The RoboArm X9 and RoboArm X9 Pro extend to a 3-year warranty when registered within 30 days of purchase at acme.com/register.
- Warranty claims require a claim code in the format ARW-##### (five digits). Claim codes are issued after a diagnostic call with support -- customers cannot self-issue one.
- Water damage, drops, and unauthorized firmware modifications void the warranty immediately.
- Battery packs are covered for 1 year only, regardless of the hardware's warranty term.

Section 3: Hardware Troubleshooting Codes

- Error E-101 (Motor calibration failure): hold the RESET button for 10 seconds until the LED blinks blue, then re-run calibration from the companion app. Front Desk and Manager can both walk a customer through this.
- Error E-204 (Battery communication fault): reseal the battery pack. If the code persists after 3 attempts, the battery requires replacement under warranty.
- Error E-317 (Firmware checksum mismatch): reflash firmware via USB-C using the Acme Recovery Tool. Do not attempt this over Wi-Fi -- an interrupted OTA update is what causes this error in the first place.
- Error E-450 (Joint overcurrent protection tripped): power cycle the unit. If it recurs within 24 hours, stop use and contact support -- this can indicate a mechanical obstruction.

Section 4: When to Escalate

- Front Desk associates handle order status, general policy questions, and basic troubleshooting (E-101, E-204).
- Support Managers have access to the order and RMA systems and additionally handle E-317 and E-450 codes, plus policy exceptions up to \$200.
- The VP of Customer Success can authorize policy exceptions above \$200, coordinate with engineering on recurring hardware faults, and search the live web for parts availability and compatibility questions.
- Escalations reaching the CEO's office are reserved for cases requiring executive judgment, PR-sensitive situations, or a problem that has already failed to resolve at every lower tier.