# **WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT**

uilding No.	Street	City	Zip	Date of Inspection	Number of Pages
0000	High Street	Adelanto	95064	12/14/2015	3



Ordered by:

# TECHKNOWLEDGE 1156 HIGH STREET 143 PHAN HUY THONG SANTA CRUZ CA 95064

(012) 345-6789 (012) 345-6789 torin@techknowledge.vn Fax (012) 345-6789

Property Owner and/or Party of Interest:

Γ 143 PHAN	Report #: 10000	
NG	Registration #: TK143	
A 95064	Escrow #: 10000	
3/5-6780	☐ CORRECTED REPORT	

Report sent to:

TORIN TECHKNOWLEDGE.VN PHAN HUY THONG HCM CA 70000		
COMPLETE REPORT  LIMITED REPORT	ORT SUPPLEMENTAL REPORT	☐ REINSPECTION REPORT ☐
GENERAL DESCRIPTION: Multi level high-rise apartment complex	nspection Tag Posted: Attic	
	[7	Other Tags Posted:
An inspection has been made of the structure(s) s steps, detached decks and any other structures no		e Structural Pest Control Act. Detached porches, detached
Subterranean Termites 🗵 Drywood	Termites ☐ Fungus / Dryrot ☐	Other Findings
f any of the above boxes are checked, it indica	ates that there were visible problems in a	ccessible areas. Read the report for details on checked

**Diagram Not To Scale** 



Inspected By: PA-01 State License No. PA-01 Signature:

## **TECHKNOWLEDGE**

Page 2 of 3 insp	ection report			
10000	High Street	Adelanto	CA	95064
Address of Property Inspected		City	State	Zip
	12/14/2015 10000 10000		000	
Stamp No.	Date of Inspection	Co. Report No.	Escrow No.	

# WHAT IS A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT? READ THIS DOCUMENT. IT EXPLAINS THE SCOPE AND LIMITATIONS OF A STRUCTURAL PEST CONTROL INSPECTION AND A WOOD DESTROYING PEST & ORGANISM INSPECTION REPORT.

A Wood Destroying Pest & Organism Inspection Report contains findings as to the presence or absence of evidence of wood destroying pests and organisms in visible and accessible areas and contains recommendations for correcting any infestations or infections found. The contents of Wood Destroying Pest & Organism Inspection Reports are governed by the Structural Pest Control Act and regulations.

Some structures do not comply with building code requirements or may have structural, plumbing, electrical, mechanical, heating, air conditioning or other defects that do not pertain to wood destroying organisms. A Wood Destroying Pest & Organism Inspection Report does not contain information on such defects, if any, as they are not within the scope of the licenses of either this company, or it's employees.

The Structural Pest Control Act requires inspection of only those areas which are visible and accessible at the time of inspection. Some areas of the structure are not accessible to inspection, such as the interior of hollow walls, spaces between floors, areas concealed by carpeting, appliances, furniture or cabinets. Infestations or infections may be active in these areas without visible and accessible evidence. If you desire information about areas that were not inspected, a further inspection may be performed at an additional cost. Carpets, furniture or appliances are not moved and windows are not opened during a routine inspection.

The exterior Surface of the roof was not inspected. If you want the water tightness of the roof determined, you should contact a roofing contractor who is licensed by the Contractor's State License Board.

This company does not certify or guarantee against any leakage, such as (but not limited to) plumbing, appliances, walls, doors, windows, any type of seepage, roof or deck coverings. This company renders no guarantee, whatsoever, against any infection, infestation or any other adverse condition which may exist in such areas or may become visibly evident in such area after this date. Upon request, further inspection of these areas would be performed at an additional charge.

In the event damage or infestation described herein is later found to extend further than anticipated, our bid will not include such repairs. OWNER SHOULD BE AWARE OF THIS CLOSED BID WHEN CONTRACTING WITH OTHERS OR UNDERTAKING THE WORK HIMSELF/HERSELF.

If requested by the person ordering this report, a re-inspection of the structure will be performed. Such requests must be within four (4) months of the date of this inspection. Every re-inspection fee amount shall not exceed the original inspection fee.

Wall paper, stain, or interior painting are excluded from our contract. New wood exposed to the weather will be prime painted, only upon request at an additional expense.

This company will reinspect repairs done by others within four months of the original inspection. A charge, if any, can be no greater than the original inspection fee for each reinspection. The reinspection must be done within ten (10) working days of request. The reinspection is a visual inspection and if inspection of concealed areas is desired, inspection of work in progress will be necessary. Any quarantees must be received from parties performing repairs.

NOTICE: Reports on this structure prepared by various registered companies should list the same findings (i.e. termite infestations, termite damage, fungus damage, etc.). However, recommendations to correct these findings may vary from company to company. You have a right to seek a second opinion from another company.

This Wood Destroying Pest & Organisms Report DOES NOT INCLUDE MOLD or any mold like conditions. No reference will be made to mold or mold-like conditions. Mold is not a Wood Destroying Organism and is outside the scope of this report as defined by the Structural Pest Control Act. If you wish your property to be inspected for mold or mold like conditions, please contact the appropriate mold professional.

## **TECHKNOWLEDGE**

Page 3 of 3 inspection report					
10000 H	igh Street	Adelanto	CA	95064	
Address of Property Inspected		City	State	Zip	
	12/14/2015	10000	10	0000	
Stamp No.	Date of Inspection	Co. Report No.	Escrow No.		

**SECTION I** CONTAINS ITEMS WHERE THERE IS EVIDENCE OF ACTIVE INFESTATION, INFECTION OR CONDITIONS THAT HAVE RESULTED IN OR FROM INFESTATION OR INFECTION.

**SECTION II** ITEMS ARE CONDITIONS DEEMED LIKELY TO LEAD TO INFESTATION OR INFECTION BUT WHERE NO VISIBLE EVIDENCE OF SUCH WAS FOUND.

**SECTION III / FURTHER INSPECTION** ITEMS ARE DEFINED AS RECOMMENDATIONS TO INSPECT AREA(s) WHICH DURING THE ORIGINAL INSPECTION DID NOT ALLOW THE INSPECTOR ACCESS TO COMPLETE HIS INSPECTION AND CANNOT BE DEFINED AS SECTION I OR II.

#### 1. SUBTERRANEAN TERMITES:

#### 1A - Section I

**FINDING**: Cellulose debris (wood, paper products) with evidence of subterranean termites was noted in the subarea. **RECOMMENDATION**: Remove and dispose of the cellulose debris of a rakable size. Chemically treat the soil at all probable entry points in the entire structure with an approved termiticide for the control of subterranean termites.

#### 1B - Section II

**FINDING**: Cellulose debris (wood, paper products) with evidence of subterranean termites was noted in the subarea. **RECOMMENDATION**: Remove and dispose of the cellulose debris of a rakable size. Chemically treat the soil at all probable entry points in the entire structure with an approved termiticide for the control of subterranean termites.

Thank you for selecting us to perform a structural pest control inspection on your property. Should you have any questions regarding this report, please call us directly by the contact information provided on the first page of the inspection report.

Our inspectors have determined that your property will benefit from a safe application of chemicals commonly used for structural pest control. In accordance with the laws and regulations of the State of California, we are required to provide you and your occupants with the following information prior to any application of chemicals to such property.

Please take a few moments to read and become familiar with the content. State law requires that you be given the following information:

**CAUTION - PESTICIDES ARE TOXIC CHEMICALS.** Structural pest control companies are registered and regulated by the Structural Pest Control Board, and apply pesticides which are registered and approved for use by the California Department of Food and Agriculture and the United States Environmental Protection Agency. Registration is granted when the state finds that based on scientific evidence, there are no appreciable risks weighted by the benefits. The degree of risk depends on the degree of exposure, so exposure should be minimized.

If within 24 hours following application, you experience symptoms similar to common seasonal illness comparable to the flu, contact your physician or poison control center and your pest control operator immediately.

For further information, contact any of the following agencies in your area:

Poison Control Center	(800) 222-1222
Structural Pest Control Board	(916) 561-8700
Agricultural Department	(909) 387-2105
Health Department	(800) 722-4794

10000 High Street Address of Property Inspected Adelanto City CA State 95064 Zip









