

Fig. 3-2: Low pass filter corner frequencies versus contact resistance. The curves represent the frequencies at which response is attenuated by 50%.

Table 3-2: Low Pass Filter Settings

Contact Resistance	Maximum Filter Setting
<10kΩ	Weak
<3kΩ	Medium
<1kΩ	Strong

## To set the low pass filter:

 Select either Weak, Medium, or Strong filtering, according to the electrode resistance:



Note To accurately measure contact resistance ≥2000Ω, you must disconnect the E-lines from the MTUMTU-A. Measure from the ground terminal to each E-line end, and between the two E-line ends of each dipole.

9 Chapter 3

Setting filter parameters