

RO Number: 3800

Inspection Number: 3121419

Year: 2016

Insurance: ALLSTATE NORTH AMERICAN INSURANCE
COMPANY

Make: Honda

Model: Pilot EX-L AWD w/Honda Sensing

VIN: 5FNYP6H64GB058105

Estimator: Shulin, CJ

IMPORTANT! Please validate vehicle is equipped with listed ADAS system components by performing a visual inspection!

Scanning Requirements

Pre & Post Scan Requirements

<https://techinfo.honda.com/rjanisis/pubs/web/ASP04485.pdf>

It is the position of American Honda that all vehicles* involved in a collision† must have the following minimum diagnostic scans, inspections, and/or calibrations done to avoid improper repair: A preliminary diagnostic scan during the repair estimation phase to determine what diagnostic trouble codes (DTCs) may be present, so proper repairs may be included. (See "Background on Scan Requirements" on PDF for more information. A post-repair diagnostic scan to confirm that no DTCs remain. Any repair that requires disconnection of electrical components in order to perform the repair will require a post-repair diagnostic scan to confirm if the component is reconnected properly and functioning. Damage that requires the replacement of body parts will always require a post-repair diagnostic scan.

Identified ADAS Related Services to be Performed

Based on the estimate, the following calibrations/initializations have been identified:

ADAS L3: Static - A & ADAS L2: Dynamic Calibration (1)

ADAS L3: Static Calibration - A (2)

Seat Belt Inspection (1)

Seat Related Calibration (1)

Recommendations

OPUS recommends a pre-scan on this vehicle. To determine what type of scan should be performed, refer to service information and certification requirements.

OPUS recommends utilizing OEM software to perform a post-scan on this vehicle.

Calibrations

ADAS System/Components

Location

Calibration

Adaptive Cruise Control

Millimeter Wave Radar

Front Bumper

ADAS L3: Static Calibration - A

Calibrate the Millimeter Wave Radar Sensor if:

- There's an SRS deployment
- Diagnostic Trouble Code (DTC) stating misalignment/error (follow diagnostic procedures first)
- Structural damage beyond minor cosmetic abrasions to any of the welded, riveted panels, or bonded parts of the main unibody
- Beyond minor cosmetic abrasions damage to the bolt-on front bulkheads, front or rear bumper impact bars, or door intrusion beams.

- Front bumper repairs within 300mm of the Millimeter Wave Radar Sensor

Any of the following is removed, installed, replaced, or adjusted:

- Millimeter Wave Radar Sensor
- Radar bracket
- Bulkhead (radiator support)

ADAS targets are required for system calibration.

Before calibrations occurs the vehicle requires:

- Full tank of fuel
- Correct tire sizes and pressures
- Unmodified suspension
- No excessive weight in the trunk of the vehicle

NOTE: A four-wheel alignment is required if suspected to be out of spec or after a collision repair but an ADAS calibration is not required in the event a four-wheel alignment is performed.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3121419&adasChecklistMatrixVehicle=1134&type=1&model=Pilot EX-LAWD w/Honda Sensing)

[adasInspection=3121419&adasChecklistMatrixVehicle=1134&type=1&model=Pilot EX-LAWD w/Honda Sensing](https://opusadas.z13.web.core.windows.net/links?adasInspection=3121419&adasChecklistMatrixVehicle=1134&type=1&model=Pilot EX-LAWD w/Honda Sensing)

Blind Spot Monitoring Systems

LaneWatch Camera

Side Mirrors

ADAS L3: Static Calibration - A

Calibrate the LaneWatch Camera after:

- Adjusting the right front door
- Any collision repairs to right front door
- Removing, installing, or replacing any of the following: LaneWatch Camera, right front outside mirror assembly, or right front door assembly

Before calibration the vehicle requires:

- Full tank of fuel
- Correct tire size and pressure
- Unmodified suspension
- No excessive weight in the trunk of the vehicle

ADAS targets are required for system calibration.

NOTE: A scan tool is not necessary for the calibration portion of this procedure; the radio head unit functions are used through a series of button presses.

NOTE: A four-wheel alignment is required if suspected to be out of spec, but an ADAS calibration is not required in the event a four-wheel alignment is performed.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3121419&adasChecklistMatrixVehicle=1305&type=1&model=Pilot EX-L AWD w/Honda Sensing)

[adasInspection=3121419&adasChecklistMatrixVehicle=1305&type=1&model=Pilot EX-L AWD w/Honda Sensing](https://opusadas.z13.web.core.windows.net/links?adasInspection=3121419&adasChecklistMatrixVehicle=1305&type=1&model=Pilot EX-L AWD w/Honda Sensing)

Lane Departure / Keep Systems

FCW/LDW Camera

Windshield

ADAS L3: Static - A & ADAS L2: Dynamic
Calibration

Aim the Multipurpose Camera if:

- There is an SRS deployment
- Diagnostic Trouble Code (DTC) stating misalignment/error (follow diagnostic procedures first)
- Structural damage beyond minor cosmetic abrasions to any of the welded, riveted panels, or bonded parts of the main unibody
- Beyond minor cosmetic abrasions damage to the bolt-on front bulkheads, front or rear bumper impact bars, or door intrusion beams.

Any of the following is removed, installed, replaced, or adjusted:

- Windshield
- Multipurpose Camera NOTE: Honda requires OEM Glass

ADAS targets are required for system calibration and immediately followed up with a dynamic adjustment.

Before calibrations occurs, the vehicle requires:

- Full tank of fuel
- Correct tire sizes and pressures
- Unmodified suspension
- No excessive weight in the trunk of the vehicle

NOTE: A four wheel alignment is required if suspected to be out of spec or after a collision repair, but camera aiming is not required in the event a four wheel alignment is performed.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3121419&adasChecklistMatrixVehicle=2866&type=1&model=Pilot EX-L AWD w/Honda Sensing)

[adasInspection=3121419&adasChecklistMatrixVehicle=2866&type=1&model=Pilot EX-L AWD w/Honda Sensing](https://opusadas.z13.web.core.windows.net/links?adasInspection=3121419&adasChecklistMatrixVehicle=2866&type=1&model=Pilot EX-L AWD w/Honda Sensing)

Occupant Detection

Occupant Classification System

Passenger Seat

Seat Related Calibration

Honda states that after any collision and regardless of damage, that a "Passenger Seat Weight Output Check" must be performed. The passenger seat must be empty and upright in a middle of track position when performing the check. If the passenger seat is removed for any reason the same check must be performed.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3121419&adasChecklistMatrixVehicle=4375&type=1&model=Pilot EX-L AWD w/Honda Sensing)

[adasInspection=3121419&adasChecklistMatrixVehicle=4375&type=1&model=Pilot EX-L AWD w/Honda Sensing](https://opusadas.z13.web.core.windows.net/links?adasInspection=3121419&adasChecklistMatrixVehicle=4375&type=1&model=Pilot EX-L AWD w/Honda Sensing)

Seat Belt Inspection

Seat Belt

Interior

Seat Belt Inspection

The seat belt system needs to be checked and components potentially replaced after any collision that results in

ne deployment of seat belt tensioners or airbags, or after moderate to severe collisions. Always inspect for physical damage, check for system errors with a scan tool, and ensure all components are functioning correctly before returning the vehicle to service.

Seatbelts must be inspected after a collision to ensure passenger safety even if the airbags have not deployed. Note: The deployment record should be checked with a scan tool to verify there are no deployments. Honda vehicles will sometimes not set fault codes to indicate deployments, this data should be investigated within the Honda Deployment Record.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3121419&adasChecklistMatrixVehicle=4413&type=1&model=Pilot EX-L AWD w/Honda Sensing)

[adasInspection=3121419&adasChecklistMatrixVehicle=4413&type=1&model=Pilot EX-L AWD w/Honda Sensing](https://opusadas.z13.web.core.windows.net/links?adasInspection=3121419&adasChecklistMatrixVehicle=4413&type=1&model=Pilot EX-L AWD w/Honda Sensing)

Identified ADAS Systems

<u>System</u>	<u>Component</u>	<u>Location</u>
Adaptive Cruise Control	Millimeter Wave Radar	Front Bumper
Blind Spot Monitoring Systems	LaneWatch Camera	Side Mirrors
Lane Departure / Keep Systems	FCW/LDW Camera	Windshield
Occupant Detection	Occupant Classification System	Passenger Seat
Seat Belt Inspection	Seat Belt	Interior
Steering Angle Sensor	Steering Angle Sensor	Column

The Fine Print:**The Fine Print (Legaleze)**

The ADAS MAP™ report is for informational purposes only and should not be considered as a replacement for Original Equipment Manufacturers (OEM) diagnostic, repair or calibration recommendations and procedures. The ADAS MAP™ platform utilizes data from multiple sources such as VIN, ADAS and safety system build data. While this data is considered accurate, Auto Techcelerators, LLC. makes no guarantees about its accuracy or completeness because it is being generated and delivered by third-parties.