

RO Number: 852898

Inspection Number: 3183755

Year: 2023

Insurance: STATE FARM INSURANCE COMPANIES

Make: Kia

Model: Sorento Hybrid SX Prestige AWD

VIN: KNDRKDLG6P5210052

Estimator:

IMPORTANT! Please validate vehicle is equipped with listed ADAS system components by performing a visual inspection!

Scanning Requirements

PRE AND POST SCANS REQUIRED

<https://kiatechinfo.snapon.com/Forms/KiaPrePostScanningPositionStatement.pdf>

After a collision has occurred, it is imperative to perform both pre-repair and post-repair scan procedures within all the systems to test for potential diagnostic trouble codes (DTCs). The DTCs may be stored in specific modules such as the airbag, body engine, or powertrain control units. The DTCs can provide information about these and other components, such as sensors, cameras, and radars (if equipped), used in the vehicle's safety systems and equipment.

Identified ADAS Related Services to be Performed

Based on the estimate, the following calibrations/initializations have been identified:

ADAS L3: Static Calibration - A (2)

Recommendations

OPUS recommends a pre-scan on this vehicle. To determine what type of scan should be performed, refer to service information and certification requirements.

OPUS recommends utilizing OEM software to perform a post-scan on this vehicle.

Calibrations

<u>ADAS System/Components</u>	<u>Location</u>	<u>Calibration</u>
Adaptive Cruise Control		
Front Radar Sensor - SCC / AEB / FCW	Front Bumper	ADAS L3: Static Calibration - A

Perform the front radar angle inspection and adjustment when:

- radar sensor is installed or replaced
- damage occurs within the immediate surrounding areas or attached parts
- a DTC for failure of calibration is present (follow diagnostic procedures first)
- the recognition and detection function has a problem

Note: ADAS targets are required for adjustment.

Bumper assembly removal is required for Vertical Angle Inspection and reinstalled for target aiming adjustment. Additional bumper removal may be required if aiming results are not within specifications.

OEM Reference:

<https://opusadas.z13.web.core.windows.net/links?>

adasInspection=3183755&adasChecklistMatrixVehicle=2803&type=1&model=Sorento Hybrid SX Prestige AWD

Surround View Systems

Surround View Monitor (SVM) Cameras Front Bumper / Side Mirrors / Trunk Lid ADAS L3: Static Calibration - A

Calibrate the Surround View Monitor (SVM) when conducting body repairs/operations that causes focus of wide camera to change, and removing, installing, replacing camera, replacing mirror or SVM unit. ADAS targets are required for system calibration.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3183755&adasChecklistMatrixVehicle=1908&type=1&model=Sorento Hybrid SX Prestige AWD)

adasInspection=3183755&adasChecklistMatrixVehicle=1908&type=1&model=Sorento Hybrid SX Prestige AWD

Identified ADAS Systems

<u>System</u>	<u>Component</u>	<u>Location</u>
Adaptive Cruise Control	Front Radar Sensor - SCC / AEB / FCW	Front Bumper
Blind Spot Monitoring Systems	Blind Spot Sensors	Rear Bumper
Lane Departure / Keep Systems	Front View Camera	Windshield
Occupant Detection	Occupant Classification System	Passenger Seat
Seat Belt Inspection	Seat Belt	Interior
Steering Angle Sensor	Steering Angle Sensor	Column
Surround View Systems	Surround View Monitor (SVM) Cameras	Front Bumper / Side Mirrors / Trunk Lid

The Fine Print:

The Fine Print (Legaleze)

The ADAS MAP™ report is for informational purposes only and should not be considered as a replacement for Original Equipment Manufacturers (OEM) diagnostic, repair or calibration recommendations and procedures. The ADAS MAP™ platform utilizes data from multiple sources such as VIN, ADAS and safety system build data. While this data is considered accurate, Auto Techcelerators, LLC. makes no guarantees about its accuracy or completeness because it is being generated and delivered by third-parties.