



Voltage
N.O.P

Hillview Motors
Robert Schimzki 5309 Route 30
Greensburg, PA 15601

RO Number:

Inspection Number: 3216112

Year: 2021

Insurance: ALLSTATE FIRE AND CASUALTY INSURANCE
COMPANY

Make: Mercedes-Benz
Model: GLC 300 4MATIC
VIN: W1N0G8EB1MV270084

Estimator: TURCHECK, ERIC

IMPORTANT! Please validate vehicle is equipped with listed ADAS system components by performing a visual inspection!

Scanning Requirements

PRE AND POST SCANS REQUIRED

[https://oem1stop.com/sites/default/files/MBUSA_Pos_Diagnostic-Repairs-following-a-Collision\(1-17\).pdf](https://oem1stop.com/sites/default/files/MBUSA_Pos_Diagnostic-Repairs-following-a-Collision(1-17).pdf)

As of model year 1996 (OBDII), vehicles involved in a collision repair should have these systems evaluated using an up-to-date Xentry Kit diagnostics computer: - Pre-repair scanning and diagnosis of the vehicle is highly recommended. The pre-repair scan will reveal any potential issues early in the estimating and repair process to allow for a more complete estimate of repairs. - Post-repair scanning and diagnosis of the vehicle is necessary to ensure that the vehicle's safety and driver-assist systems are operable and fully functioning. Many of the safety and driver-assist systems that may have been activated during a collision require vehicle calibration, normalization, or coding.

Identified ADAS Related Services to be Performed

Based on the estimate, the following calibrations/initializations have been identified:

ADAS L2: Dynamic Calibration (2)
Seat Belt Inspection (1)

Recommendations

OPUS recommends a pre-scan on this vehicle. To determine what type of scan should be performed, refer to service information and certification requirements.

OPUS recommends utilizing OEM software to perform a post-scan on this vehicle.

Calibrations

<u>ADAS System/Components</u>	<u>Location</u>	<u>Calibration</u>
Adaptive Cruise Control		
DISTRONIC Sensor	Front Bumper	ADAS L2: Dynamic Calibration

DISTRONIC Plus requires calibration and SCN programming if the radar unit is replaced. Xentry will need to be connected throughout the dynamic calibration drive cycle. ADAS targets are not required for system calibration.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3216112&adasChecklistMatrixVehicle=2572&type=1&model=GLC 300 4MATIC)

[adasInspection=3216112&adasChecklistMatrixVehicle=2572&type=1&model=GLC 300 4MATIC](https://opusadas.z13.web.core.windows.net/links?adasInspection=3216112&adasChecklistMatrixVehicle=2572&type=1&model=GLC 300 4MATIC)

Collision Warning / Avoidance Systems

Active Brake Assist	Front Bumper	ADAS L2: Dynamic Calibration
---------------------	--------------	------------------------------

Active Brake Assist requires calibration if the front bumper is removed, replaced, or if the module is removed or replaced. ADAS targets are not required for system calibration.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3216112&adasChecklistMatrixVehicle=2572&type=1&model=GLC 300 4MATIC)

adasInspection=3216112&adasChecklistMatrixVehicle=3659&type=1&model=GLC 300 4MATIC

Seat Belt Inspection

Seat Belt

Interior

Seat Belt Inspection

Seatbelts must be inspected after a collision to ensure passenger safety. While ADASMap and Alldata serve as valuable resources to assist in the repair process, it is ultimately the responsibility of the repair professional to follow proper procedures and safety guidelines. For the most accurate and up-to-date information, always consult the vehicle manufacturer's service manual when available.

OEM Reference:

<https://opusadas.z13.web.core.windows.net/links?>

adasInspection=3216112&adasChecklistMatrixVehicle=4424&type=1&model=GLC 300 4MATIC

Identified ADAS Systems

<u>System</u>	<u>Component</u>	<u>Location</u>
Adaptive Cruise Control	DISTRONIC Sensor	Front Bumper
Backup Cameras	Backup Camera	Trunk Lid
Blind Spot Monitoring Systems	Blind Spot Assist	Rear Bumper
Collision Warning / Avoidance Systems	Active Brake Assist	Front Bumper
Lane Departure / Keep Systems	Augmented Reality Camera	Windshield
	Multifunction Camera	Windshield
Occupant Detection	Occupant Detection System	Passenger Seat
Seat Belt Inspection	Seat Belt	Interior
Steering Angle Sensor	Steering Angle Sensor	Column

The Fine Print:

The Fine Print (Legaleze)

The ADAS MAP™ report is for informational purposes only and should not be considered as a replacement for Original Equipment Manufacturers (OEM) diagnostic, repair or calibration recommendations and procedures. The ADAS MAP™ platform utilizes data from multiple sources such as VIN, ADAS and safety system build data. While this data is considered accurate, Auto Techcelerators, LLC. makes no guarantees about its accuracy or completeness because it is being generated and delivered by third-parties.