3 Rc 7.3 JL 50mA/

3,3 - 0,7 = 2.6V

 $\frac{26V}{220} = 0.0118 = 11.8 \text{ mA}$

ICMAX = 2360 MA

6P10 - 9 MODE 18 PWM 6910-9 WRITE 18 1 3 CHECK PIN 12 6910-9 WRITE 18 0 3 CHECK PIN 12 TOGGLES

5V-92=4,8

Ic = 300mA

Ri= 4.8 = 16

RL=10 RMIN

Ic = 175mA

R1 = 2012

TX: 5,6 mA @5V. 434 MHZ RX: 3,6 MA