	Person(s) testing & location:	Pius Wong	VxAustin	
	Date & time tested		Afternoon	
	System tested & Unit/Model No.:	9/3/2024 VxScan v4.0	Build 0 unit 3	
	Before what other test?			
	After what other test?	Cold storage test Drop test, bench handling		
	After what other test:	Drop test, benc	in nanuling	
Alway	vs do these:			
Aiway	s do these.	Pass / Fail /		
No.	Test	Mixed?	Notes	
1	Scans ballots and saves cast-vote records (CVRs).	PASS	tested 12 ballots, 8.5x14, 10 hand-marked, 2 machine-marked, from UAT	
2	Stores ballots securely in the ballot box.	n/a	no ballot box	
3	Prints accurate reports before and after scanning ballots.	PASS	3 good printouts	
			tested inputting thermal paper report, blank sheets, multiple ballots; no	
4	Rejects invalid ballots and double-sheet ballots.	PASS	need to recalibrate MSD	
5	Displays instructions and accurate feedback to users visually and audibly.	PASS		
6	Accepts user inputs on a touchscreen.	PASS		
Some	times do these (after environmental, vibrational, or othe	er mechanical te	ests):	
No.	Test	Pass / Fail / Mixed?	Notes	
	Main control module (MCM) attaches to and detaches			
7	from the ballot box easily.	n/a	no ballot box	
8	Maintains physical security, restricting administrative access and preventing tampering without evidence.	n/a	no ballot box	
9	Protects internal electronics and subsystems.	PASS		
10	Stores emergency ballots when the ballots cannot be processed automatically.	n/a	no ballot box	
Inspe	ction of parts, after tests of normal function above:		(this was after opening it up to reattach loose pollworker door hinge bolt & nut)	
No.	Part	Visual condition	isual conditio notes	
1	Scanner	PASS	only opened external panels from bottom tub	
	Thermal Printer	PASS	only opened external panels from bottom tub	
	Computer	PASS	only opened external panels from bottom tub	
	Touch/Screen	PASS	only opened external panels from bottom tub	
	Power Supply (internal to MCM)	PASS	only opened external panels from bottom tub	
	Uninterruptible Power Supply (external to MCM)	n/a	did not test	
	JavaCard Reader	PASS	only opened external panels from bottom tub	
	Speaker + Amp	n/a	only opened external panels from bottom tub	
	USB-A female receptacles	n/a	only opened external panels from bottom tub	
	Cable Assemblies	PASS	only opened external panels from bottom tub	
11	Outer case	PASS	only opened external panels from bottom tub	
	Inner panels around electronics	PASS	only opened external panels from bottom tub	
	Locking mechanism of main control module (MCM) on the ballot box	MIXED	no ballot box; works, but horizontal thumb slide is loose	
	Security tie points	PASS	only opened external panels from bottom tub	
	y p			

15	Fasteners, both external and internal	FAIL	loose bolt and nut from pollworker door; needs locking mechanism: e.g. locknuts> this was refastened after opening up and investigating for any other loose parts
16	Wires, ports, and electrical connections	PASS	only opened external panels from bottom tub
17	Ballot box	n/a	no ballot box
18	other		
	mains power port	MIXED	missing top screw (on purpose from Pump), but still secure
	rear power cord holder	n/a	not included in current unit