Corre	sponds to detailed doc here:	https://docs.goo	ngle.com/document/d/1Spdm13rntVPqr1FWzQiuTmhqo_elKyV9OPynhBoo0EM/edit#headinq=h.uc9eo131qpe	h	
00110	Person(s) testing & location:	Pius Wong	VxAustin	<u> </u>	
	Date & time tested		afternoon		
	System tested & Unit/Model No.:	VxScan v4.0			
	Before what other test?	Cold storage te			
	After what other test?	-	(closed configuration)		
	Arter what other test:	drop test, basic	(closed corniguration)		
Δlwa	vs do these:				
Aiwa	s do triese.	Pass / Fail /			
No.	Test	Mixed?	Notes		
1	Scans ballots and saves cast-vote records (CVRs).	PASS	tested 12 ballots, 8.5x14, 10 hand-marked, 2 machine-marked, from UAT		
2	Stores ballots securely in the ballot box.	n/a	no ballot box to test		
3	Prints accurate reports before and after scanning ballots.	PASS	3 good printouts		
4	Rejects invalid ballots and double-sheet ballots.	PASS	tested inputting thermal paper report, blank sheets, multiple ballots; no need to recalibrate MSD		
5	Displays instructions and accurate feedback to users visually and audibly.	PASS			
6	Accepts user inputs on a touchscreen.	PASS			
Some	times do these (after environmental, vibrational, or othe	er mechanical te	ests):		
		Pass / Fail /			
No.	Test	Mixed?	Notes		
7	Main control module (MCM) attaches to and detaches from the ballot box easily.	n/a	no ballot box		
8	Maintains physical security, restricting administrative access and preventing tampering without evidence.	n/a	no ballot box		
9	Protects internal electronics and subsystems.	PASS			
10	Stores emergency ballots when the ballots cannot be processed automatically.	n/a	no ballot box		
Inspection of parts, after tests of normal function above:			(this was after opening it up to reattach loose pollworker door hinge bolt & nut)		
No.	Part	Visual condition	notes		
1	Scanner	PASS	only opened external panels from bottom tub		
2	Thermal Printer	PASS	only opened external panels from bottom tub		
3	Computer	PASS	only opened external panels from bottom tub		
4	Touch/Screen	PASS	only opened external panels from bottom tub		
5	Power Supply (internal to MCM)	PASS	only opened external panels from bottom tub		
6	Uninterruptible Power Supply (external to MCM)	n/a	did not test		
	JavaCard Reader	PASS	only opened external panels from bottom tub		
8	Speaker + Amp	n/a	only opened external panels from bottom tub		
	USB-A female receptacles	n/a	only opened external panels from bottom tub		
	Cable Assemblies	PASS	only opened external panels from bottom tub		
11	Outer case	PASS	only opened external panels from bottom tub		
12	Inner panels around electronics	PASS	only opened external panels from bottom tub		
13	Locking mechanism of main control module (MCM) on the ballot box	MIXED	no ballot box; works, but horizontal thumb slide is loose		
14	Security tie points	PASS	only opened external panels from bottom tub		

15 Fasteners, both external and internal	FAIL	loose bolt and nut from pollworker door; needs locking mechanism: e.g. locknuts> this was refastened after opening up and investigating for any other loose parts			
16 Wires, ports, and electrical connections	PASS	only opened external panels from bottom tub			
17 Ballot box	n/a	no ballot box			
18 other					
mains power port	MIXED	missing top screw (on purpose from Pump), but still secure			
rear power cord holder	missing	missing			