

OEM Quality Alert - Root Cause Report

Critical Finding:

ECU - Batch D009 from National Parts

has caused 4 failures (8.0%) in the last 90 days.

Recommended Corrective & Preventive Actions (CAPA):

- Immediately halt use of Batch D009
- Switch to alternate supplier ABC Industries (0 failures recorded)
- Initiate 8D root cause analysis within 48 hours
- Notify all affected vehicles for recall inspection