VR Inspector | Inspection Report

SAMPLE REPORT - demo data only

Project	Cedar Hollow Landfill RNG (sample)
Inspection	Flare & condensate system walkdown
Inspector	Demo Inspector
Status	Signed off by Demo Inspector
Report version	v1

Findings (3)

High Flare KO drum level transmitter LT-452 not calibrated
Resolved: calibration cert attached

Medium Condensate drain valve at V-101 missing tag
Resolved: tag installed

Low Touch-up paint on T-450 ladder
Resolved

Site photos (2)



