





Shift and Carry Gate Control	
TITLE: pdp81	
Document Number: D-BS-8L-0-5	REV:
Date: 2/21/2016 2:59:50 PM	Sheet: 4/23




Interrupt and Break Control		
TITLE: pdp8l		
Document Number: D-BS-8L-0-7		REV:
Date: 2/21/2016 2:59:50 PM		Sheet: 6/23



DEC panel does not connect PCnn.



Major Registers		
TITLE: pdp81		
Document Number: D-BS-8L-0-8		REV:
Date: 2/21/2016 2:59:50 PM		Sheet: 7/23



Major Register Gating (Sheet 1)


TITLE: pdp81

Document Number: 0-BS-8L-0-9

REV:

Date: 2/21/2016 2:59:50 PM

Sheet: 8/23



Major Register Gating (Sheet 3)


TITLE: pdp81

Document Number: D-BS-8L-0-9

REV:

Date: 2/21/2016 2:59:50 PM

Sheet: 10/23



Major Register Gating (Sheet 4)


TITLE: pdp81


Document Number: 0-BS-8L-0-9

REV:

Date: 2/21/2016 2:59:50 PM

Sheet: 11/23







UCC
GND

Teletype Receiver		
TITLE: pdp81		
Document Number: D-BS-8L-0-11		REV:
Date: 2/21/2016 2:59:50 PM	Sheet: 13/23	



Teletype Transmitter	
TITLE: pdp8l	
Document Number: D-B8-8L-0-12	REV:
Date: 2/21/2016 2:59:50 PM	Sheet: 14/23



* Used with MP8L

VCC
 GND
 -16V

Sense Amps and Inhibit Drivers

TITLE: pdp8l

Document Number: D-BS-8L-0-14


REV:

Date: 2/21/2016 2:59:50 PM


Sheet: 16/23



X-Axis Selection	
TITLE: pdp81	
Document Number: D-B5-8L-0-15	REV:
Date: 2/21/2016 2:59:50 PM	Sheet: 17/23




* G611 in CD22 is replaced with G612 for MP8L.




VCC
GND

Y-Axis Selection		
TITLE: pdp8l		
Document Number: D-BS-8L-0-16		REV:
Date: 2/21/2016 2:59:50 PM		Sheet: 18/23



Misc. Connections	
TITLE: pdp8l	
Document Number: D-B5-8L-0-17	REV:
Date: 2/21/2016 2:59:50 PM	Sheet: 19/23



Power Failure


TITLE: pdp8l

Document Number: D-BS-KP8L-0-1

REV:

Date: 2/21/2016 2:59:50 PM

Sheet: 20/23



Punch Control	
TITLE: pdp81	
Document Number:	REV:
Date: 2/21/2016 2:59:50 PM	Sheet: 21/23

Reader Control




TITLE: pdp81

Document Number:


REV:

Date: 2/21/2016 2:59:50 PM

Sheet: 22/23



Borrowed Gates from A14 may not match DEC implementation.



VCC
GND

Memory Parity	
TITLE: pdp8l	
Document Number:	REV:
Date: 2/21/2016 2:59:50 PM	Sheet: 23/23