


# CLA Systems

P?S/8 System Device Handler for TD8E with  
MR8E-C ROM [assembly listing] [Note: Work in Progress]



P?S/8

Name: TDRM  
Document: P?S/8 System Device Handler for DEC TD8E with MR8E-C ROM  
File[s]: PQSTDR.LST  
P?S Index: O>R,SCQL  
Security Level: 2  
Location: NY  
Date: 28-Feb-2016  
Medium: PDF

Notice: This document is a copyrighted work of CLA Systems and is not a product of Digital Equipment Corporation [DEC].

In certain instances, portions of the P?S/8 operating system [for the PDP-8 or compatible products] or its subcomponents are based on products originally created by DEC personnel; in some instances before they were employees of DEC. Generally, the nature of the CLA Systems product [P?S/8] is such that any role played by any DEC products is incidental to the overall purpose of the CLA Systems product; in all such instances, DEC's copyright will be either clearly stated or implied. [Note: P?S/8 in one form or another (including the forerunner R-L Monitor System) was offered to DEC several times; however the software was rejected only due to the indifference of incompetent DEC management personnel overruling their programming staff members despite their serious interest, encouragement, and in some cases lobbying.]

A release of P?S/8 was marketed by the Intersil Corporation under the name IFDOS [Intercept Floppy Disk Operating System]. However, that release was only for a specific early version of P?S/8 configured for the RX01 [or compatible] with 8K of memory [or more]. Intersil has specific limited rights to only that version of P?S/8; in every other instance, all rights remain with CLA Systems.

Due to the highly compatible nature of P?S/8, various DEC utility programs may be offered with specific releases for the convenience of the user; generally, little or no changes are made to these programs other than initialization routines to cause the program to conform to all relevant P?S/8 requirements [or perhaps to eliminate program bugs]. [These considerations generally apply to programs written to be run as standalone binary paper tapes that may violate certain storage-based operating system conventions. In certain instances, erroneous model dependencies were added by incompetent DEC programmers in an attempt to adapt the programs to OS/8.]