

Parts List

1. 12.6 V LiPo Battery 3000 mAh
2. Fuse (optional)
3. Switch
4. 12.6 V to 5 V DC Buck Converter
5. Arduino Mega 2560
6. PCA9685 Servo Controller
7. 1 to 2 Lever Wire Connectors (optional)
8. M2, M2.5, M3 screws
9. Jumper Wires