


with lever stop on Tip and Low position



Main Data	
Working medium	Air
Operating pressure (Bar)	Mín. 5; Máx. 10
Working temperature	- 30°C / + 80 °C
Thread ports	G1/8"

ABER is constantly engaged in improving its products and, therefore, reserves itself the right to modify without any further notice the characteristics shown

