

Greetech Razer Green		
17	/35	Push Feel
13	/25	Wobble
3	/10	Sound
6	/20	Context
4	/10	Other
43	/100	Total

# **Notes**

# **Push Feel**

Greetech Razer Greens are certainly an interesting feeling switch. Aside the same thick bottoming out, thin topping out, and heavy scratch notes present in the other two Greetech Razer switches, these feature a very unique mushy, almost grainy like feeling click jacket mechanism which doesn't do much to aid in the already flat, lifeless feeling click bump.

#### Wobble

While not altogether out of the realm of commonplace for 2015 Greetech switches, these Razer branded switches have a large amount of N/S and E/W stem wobble in addition to an E/W top housing wobble due to poor mold matching between top and bottom halves.

### Sound

These are a nightmare in the clicky-switch sound department. While already having a muted, flat, and lifeless click point, the sound is nearly drowned out by loud spring ping, mechanical crunching, and sporadic 'metallic' sounds.

### Context

While these were only featured briefly in 2015 Razer branded keyboards, these take an extra hit compared to other Greetech Razers because these are significantly below par compared to other clicky switches available at the time, something which Razer, as a gameroriented company should be focused on even more due to their preference among "gamers".

# Other

These are not only the worst of the Greetech Razer options, but among some of the worst MX style clicky switches I've seen. I'm quite thankful that these are merely going to be remembered as a footnote in Razer's ever-changing switch manufacturer history line.