

LALA HARYDAL PARK — ASSET INVENTORY

Category export · AI Drone Survey · DDA / DTU parameter framework
Site: Lala Harydal Park, North Delhi (DDA)
Survey date: 19 May 2026, 11:49-12:12 IST (single-date baseline)
Category: Asset Inventory

DETECTOR FINDINGS

Detector class	Records	Mean cond. %	Worst %	Condition
Tree Stem	1767	95.5	69.3	Good
Bench	282	80.5	70.4	Good
Play Equipment	681	82.2	61.6	Good
Open Gym Equipment	331	79.3	58.7	Good
Walking Track	178	54.7	29.6	Poor

ANOMALIES (worst first)

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
10	Palm avenue & lawns	Walking Track	High	33.1	Resurface / patch the track; restore edge definition and camber.
53	Formal beds & pathways	Walking Track	High	42.2	Resurface / patch the track; restore edge definition and camber.
227	Formal beds & pathways	Walking Track	Medium	52.7	Resurface / patch the track; restore edge definition and camber.
327	Formal beds & pathways	Walking Track	Medium	59.8	Resurface / patch the track; restore edge definition and camber.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
6	Low	Tree tree cover, topiary, kerbs, benches and paved avenues are all in reasonable condition.	Maintain the current regime for planting and hardscape; the investment needed is in the ground plane.	Horticulture Division
8	Process	The saturated-colour rule reports 681 play-equipment and 331 gym-equipment records in a park where none was observed - it is catching red benches and planter edging.	Treat those two rows as unverified. A scene-level gate similar to the one used for construction can suppress them per park on request.	Survey / Drone Cell

Generated from Lala_Hardeval_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 3 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.