

LALA HARYDAL PARK — IRRIGATION STATUS

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Lala Harydal Park, North Delhi (DDA)

Survey date: 19 May 2026, 11:49-12:12 IST (single-date baseline)

Category: Irrigation Status

CATEGORY SCORE				
Indicator	Mean	Min	Max	Rating
Irrigation Efficiency	69.4%	35.4%	92%	Fair

SCENE COVERAGE (park-wide mean)			
Metric	Mean	Min	Max
Bare ground	20%	5.7%	36.6%
Dry vegetation	0.9%	0%	6.3%
Waterlogging	0.8%	0%	7.6%

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Waterlogging	78	48.5	44.6	Poor
Bare Ground Patch	1312	50.4	12.2	Poor
Dry / Dead Vegetation	363	50.3	46.9	Poor

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
1	Palm avenue & lawns	Bare Ground Patch	Critical	14.9	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
2	Palm avenue & lawns	Bare Ground Patch	Critical	19	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
18	Central axis & parterre	Bare Ground Patch	High	36.9	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
31	Formal beds & pathways	Bare Ground Patch	High	39.8	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
32	Formal beds & pathways	Bare Ground Patch	High	40	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
36	Formal beds & pathways	Bare Ground Patch	High	40.3	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
41	Palm avenue & lawns	Bare Ground Patch	High	41	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
46	Formal beds & pathways	Bare Ground Patch	High	41.5	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
47	Palm avenue & lawns	Bare Ground Patch	High	41.6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
52	Formal beds & pathways	Bare Ground Patch	High	42.1	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
54	Formal beds & pathways	Bare Ground Patch	High	42.2	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
57	Formal beds & pathways	Bare Ground Patch	High	42.7	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
63	Palm avenue & lawns	Bare Ground Patch	High	43.4	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
64	Palm avenue & lawns	Bare Ground Patch	High	43.4	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
75	Palm avenue & lawns	Bare Ground Patch	High	45	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
102	Formal beds & pathways	Bare Ground Patch	Medium	47.2	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
105	Palm avenue & lawns	Waterlogging	Medium	47.4	Investigate drainage; standing water is a slip and mosquito-breeding risk.
111	Palm avenue & lawns	Bare Ground Patch	Medium	47.6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
115	Palm avenue & lawns	Bare Ground Patch	Medium	47.8	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
128	Palm avenue & lawns	Dry / Dead Vegetation	Medium	48.5	Clear dry and dead material; prune out deadwood and irrigate.
130	Palm avenue & lawns	Bare Ground Patch	Medium	48.6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
129	Formal beds & pathways	Bare Ground Patch	Medium	48.6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
134	Palm avenue & lawns	Waterlogging	Medium	48.9	Investigate drainage; standing water is a slip and mosquito-breeding risk.
142	Palm avenue & lawns	Waterlogging	Medium	49.2	Investigate drainage; standing water is a slip and mosquito-breeding risk.
138	Formal beds & pathways	Waterlogging	Medium	49.2	Investigate drainage; standing water is a slip and mosquito-breeding risk.
143	Formal beds & pathways	Waterlogging	Medium	49.3	Investigate drainage; standing water is a slip and mosquito-breeding risk.
144	Formal beds & pathways	Dry / Dead Vegetation	Medium	49.4	Clear dry and dead material; prune out deadwood and irrigate.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
147	Formal beds & pathways	Dry / Dead Vegetation	Medium	49.5	Clear dry and dead material; prune out deadwood and irrigate.
149	Formal beds & pathways	Bare Ground Patch	Medium	49.6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
150	Formal beds & pathways	Dry / Dead Vegetation	Medium	49.6	Clear dry and dead material; prune out deadwood and irrigate.
154	Formal beds & pathways	Waterlogging	Medium	49.7	Investigate drainage; standing water is a slip and mosquito-breeding risk.
155	Central axis & parterre	Bare Ground Patch	Medium	49.7	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
158	Palm avenue & lawns	Dry / Dead Vegetation	Medium	49.9	Clear dry and dead material; prune out deadwood and irrigate.
164	Palm avenue & lawns	Bare Ground Patch	Medium	50	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
165	Palm avenue & lawns	Dry / Dead Vegetation	Medium	50.1	Clear dry and dead material; prune out deadwood and irrigate.
167	Palm avenue & lawns	Dry / Dead Vegetation	Medium	50.1	Clear dry and dead material; prune out deadwood and irrigate.
173	Palm avenue & lawns	Bare Ground Patch	Medium	50.3	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
175	Formal beds & pathways	Bare Ground Patch	Medium	50.4	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
176	Central axis & parterre	Bare Ground Patch	Medium	50.5	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
178	Palm avenue & lawns	Dry / Dead Vegetation	Medium	50.7	Clear dry and dead material; prune out deadwood and irrigate.

Showing the worst 40 of 122 tracked instances in this category.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
1	Critical	Bare and dry ground averages 15-23% of frame across all three zones and lawn cover is only 11-22%. This is the park's dominant defect and matches the site record.	Commission a turf reinstatement programme: decompact, level, top-dress and re-turf the failed areas, then correct the watering coverage that allowed them to fail. Prioritise the formal-beds zone.	Horticulture Division
2	High	Hoses are lying across the lawns rather than a fixed watering system operating, and the dry-patch pattern is uneven - consistent with manual watering that does not reach the whole ground plane.	Audit the watering layout against the dry-patch map in this report; install or repair fixed watering to the areas that are consistently missed.	Engineering / Horticulture

#	Priority	Finding	Recommended action	Owner
7	Process	Items recorded on site with no detector class yet: flower beds, weeds near pathways, water pipes and leakage, dustbins, gates, gazebo, signposts, streetlights, parking, boundary wall and railings as distinct classes.	Confirm which matter most for the DDA report and they can be added. Flower beds and weeds-near-pathways are both straightforward and directly relevant to this park.	Survey / Drone Cell

Generated from Lala_Hardeval_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 3 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.