

DDA PARK, ROHINI — ASSET INVENTORY

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: DDA Park, Rohini, Rohini (DDA)

Survey date: 20 May 2026, 12:12-12:43 IST (single-date baseline)

Category: Asset Inventory

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Tree Stem	2268	95.1	50	Good
Bench	96	80.8	71	Good
Play Equipment	0	—	—	Not observed in these clips
Open Gym Equipment	0	—	—	Not observed in these clips
Walking Track	126	62.9	49.1	Fair

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
167	Algal channel & banks	Walking Track	Medium	54.6	Resurface / patch the track; restore edge definition and camber.
205	Algal channel & banks	Walking Track	Medium	57	Resurface / patch the track; restore edge definition and camber.
218	Algal channel & banks	Walking Track	Medium	59.6	Resurface / patch the track; restore edge definition and camber.

RECOMMENDED ACTIONS				
#	Priority	Finding	Recommended action	Owner
6	Medium	facilities sits at 71-77 across all zones - the weakest spread of any park surveyed. Only 126 pathway and 96 bench records, and the gazebo is visibly weathered.	Survey the path network and built assets; the low detection counts suggest a fragmented and under-maintained network rather than a detector limitation.	Engineering / Works

Generated from Rohini_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 3 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.