

SANJAY LAKE — ASSET INVENTORY

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Sanjay Lake, East Delhi (DDA)

Survey date: 19 May 2026 (single-date baseline survey)

Category: Asset Inventory

DETECTOR FINDINGS					
Detector class		Records	Mean cond. %	Worst %	Condition
Tree Stem		4906	93.2	34.3	Good
Bench		511	79.4	69.3	Good
Play Equipment		2232	86.2	56.6	Good
Open Gym Equipment		1418	87.1	69.5	Good
Walking Track		556	50.6	32.3	Poor
ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
22	Children's play area	Walking Track	High	33.5	Resurface / patch the track; restore edge definition and camber.
24	Children's play area	Walking Track	High	33.8	Resurface / patch the track; restore edge definition and camber.
35	Children's play area	Walking Track	High	35.8	Resurface / patch the track; restore edge definition and camber.
42	Children's play area	Walking Track	High	36.5	Resurface / patch the track; restore edge definition and camber.
64	Children's play area	Walking Track	High	39.6	Resurface / patch the track; restore edge definition and camber.
78	Children's play area	Walking Track	High	41	Resurface / patch the track; restore edge definition and camber.
86	Children's play area	Walking Track	High	42.6	Resurface / patch the track; restore edge definition and camber.
88	Children's play area	Walking Track	High	42.7	Resurface / patch the track; restore edge definition and camber.
93	Children's play area	Walking Track	High	43.3	Resurface / patch the track; restore edge definition and camber.
104	Children's play area	Walking Track	High	44.3	Resurface / patch the track; restore edge definition and camber.
110	Children's play area	Walking Track	Medium	45.3	Resurface / patch the track; restore edge definition and camber.
112	Children's play area	Tree Stem	Medium	45.5	Check stem for lean, cavities or decay; make safe if unstable.
113	Children's play area	Walking Track	Medium	45.5	Resurface / patch the track; restore edge definition and camber.
125	Children's play area	Walking Track	Medium	47.1	Resurface / patch the track; restore edge definition and camber.
130	Children's play area	Walking Track	Medium	47.5	Resurface / patch the track; restore edge definition and camber.
147	Children's play area	Walking Track	Medium	48.5	Resurface / patch the track; restore edge definition and camber.
154	Children's play area	Walking Track	Medium	49.4	Resurface / patch the track; restore edge definition and camber.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
157	Children's play area	Walking Track	Medium	49.7	Resurface / patch the track; restore edge definition and camber.
159	Children's play area	Walking Track	Medium	49.9	Resurface / patch the track; restore edge definition and camber.
163	Children's play area	Walking Track	Medium	50.1	Resurface / patch the track; restore edge definition and camber.
204	Children's play area	Tree Stem	Medium	51.8	Check stem for lean, cavities or decay; make safe if unstable.
260	Children's play area	Tree Stem	Medium	56	Check stem for lean, cavities or decay; make safe if unstable.
275	Children's play area	Walking Track	Medium	56.8	Resurface / patch the track; restore edge definition and camber.
292	Children's play area	Walking Track	Medium	59.4	Resurface / patch the track; restore edge definition and camber.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
5	Medium	Play and gym equipment is broadly serviceable, but several units score materially below their cluster mean on the paint-integrity index.	Inspect the lowest-scoring units listed in '7. Anomalies'; sand, prime and repaint, and check all fixings, bearings and footings.	Engineering / Works
9	Process	No GPS telemetry sidecar (.SRT) accompanied any of the four clips, which blocks asset geo-tagging and the geo-tagged issue map.	Standardise the flight export to include the telemetry file so every detection can carry a coordinate.	Survey / Drone Cell

Generated from Sanjay_Lake_Park_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 1 analysed clip, recomputed directly from the detection log rather than the workbook's own summary formulas.