

SMRITI VAN MAYUR VIHAR — IRRIGATION STATUS

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Smriti Van Mayur Vihar, Mayur Vihar (DDA)

Survey date: 19 May 2026, 16:54-17:35 IST (single-date baseline)

Category: Irrigation Status

CATEGORY SCORE				
Indicator	Mean	Min	Max	Rating
Irrigation Efficiency	68.6%	31.1%	99.5%	Fair

SCENE COVERAGE (park-wide mean)			
Metric	Mean	Min	Max
Bare ground	19.1%	0.4%	45.8%
Dry vegetation	0%	0%	0%
Waterlogging	3.4%	0%	20%

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Waterlogging	331	47.4	32.6	Poor
Bare Ground Patch	816	44.9	6	Poor
Dry / Dead Vegetation	82	50.7	49	Poor

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
1	Waterlogged ground	Bare Ground Patch	Critical	6.4	Reinstate ground cover once works are complete; decompact and re-turf.
2	Flooded planting bed	Bare Ground Patch	Critical	6.7	Reinstate ground cover once works are complete; decompact and re-turf.
3	Flooded planting bed	Bare Ground Patch	Critical	17	Reinstate ground cover once works are complete; decompact and re-turf.
8	Waterlogged ground	Bare Ground Patch	Critical	21.1	Reinstate ground cover once works are complete; decompact and re-turf.
9	Waterlogged ground	Bare Ground Patch	Critical	21.9	Reinstate ground cover once works are complete; decompact and re-turf.
13	Waterlogged ground	Bare Ground Patch	Critical	29.5	Reinstate ground cover once works are complete; decompact and re-turf.
17	Waterlogged ground	Bare Ground Patch	High	31.4	Reinstate ground cover once works are complete; decompact and re-turf.
21	Flooded planting bed	Bare Ground Patch	High	34.4	Reinstate ground cover once works are complete; decompact and re-turf.
37	Children's play area	Bare Ground Patch	High	39.4	Reinstate ground cover once works are complete; decompact and re-turf.
45	Children's play area	Bare Ground Patch	High	41.7	Reinstate ground cover once works are complete; decompact and re-turf.
48	Lawns & tree belt	Bare Ground Patch	High	42.4	Reinstate ground cover once works are complete; decompact and re-turf.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
50	Children's play area	Waterlogging	High	42.5	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
53	Children's play area	Bare Ground Patch	High	43.1	Reinstate ground cover once works are complete; decompact and re-turf.
54	Children's play area	Bare Ground Patch	High	43.1	Reinstate ground cover once works are complete; decompact and re-turf.
69	Children's play area	Bare Ground Patch	Medium	45.5	Reinstate ground cover once works are complete; decompact and re-turf.
72	Children's play area	Bare Ground Patch	Medium	45.8	Reinstate ground cover once works are complete; decompact and re-turf.
73	Children's play area	Waterlogging	Medium	45.9	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
74	Lawns & tree belt	Waterlogging	Medium	46.2	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
81	Lawns & tree belt	Bare Ground Patch	Medium	47.3	Reinstate ground cover once works are complete; decompact and re-turf.
86	Waterlogged ground	Bare Ground Patch	Medium	47.7	Reinstate ground cover once works are complete; decompact and re-turf.
88	Waterlogged ground	Waterlogging	Medium	48.1	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
93	Waterlogged ground	Waterlogging	Medium	48.3	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
94	Children's play area	Waterlogging	Medium	48.4	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
95	Children's play area	Waterlogging	Medium	48.5	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
96	Waterlogged ground	Waterlogging	Medium	48.5	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
98	Waterlogged ground	Bare Ground Patch	Medium	48.6	Reinstate ground cover once works are complete; decompact and re-turf.
99	Flooded planting bed	Waterlogging	Medium	48.7	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
102	Children's play area	Bare Ground Patch	Medium	48.7	Reinstate ground cover once works are complete; decompact and re-turf.
100	Waterlogged ground	Waterlogging	Medium	48.7	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
101	Waterlogged ground	Waterlogging	Medium	48.7	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
105	Children's play area	Waterlogging	Medium	49	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
104	Waterlogged ground	Waterlogging	Medium	49	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
106	Waterlogged ground	Bare Ground Patch	Medium	49	Reinstate ground cover once works are complete; decompact and re-turf.
108	Children's play area	Bare Ground Patch	Medium	49.2	Reinstate ground cover once works are complete; decompact and re-turf.
107	Waterlogged ground	Dry / Dead Vegetation	Medium	49.2	Clear dry and dead material from the works margin.
116	Waterlogged ground	Waterlogging	Medium	49.6	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
115	Lawns & tree belt	Waterlogging	Medium	49.6	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
118	Flooded planting bed	Waterlogging	Medium	49.7	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
119	Flooded planting bed	Waterlogging	Medium	49.7	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.
117	Waterlogged ground	Waterlogging	Medium	49.7	Check drainage across the disturbed ground; standing water on a works surface is a slip and mosquito-breeding risk.

Showing the worst 40 of 85 tracked instances in this category.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
1	Critical	Standing water is lying across a planting bed and over churned open ground in two of the four zones. This matches the site record of waterlogging and over-watering as the park's main problem.	Survey and clear the surface drainage across these zones; check the watering schedule for over-watering and inspect the water pipe running through the flooded bed for a leak.	Engineering / Horticulture
2	High	Ground cover has failed across the three used zones - bare and dry ground at 23-30% of frame, lawn under 6%.	Reinstate ground cover after drainage is fixed: decompact, regrade to fall away from the beds, then re-turf and establish an watering regime matched to the corrected drainage.	Horticulture Division

#	Priority	Finding	Recommended action	Owner
4	High	A piece of children's play equipment appears collapsed on the ground in the play-area clip, and the sand surface beneath the equipment is bare and hard-packed.	Inspect and make safe immediately - remove or reinstate the fallen unit, and replace the impact-absorbing surface under all play equipment.	Engineering / Works
8	Process	Several items recorded on site have no detector class yet: leaking water pipes, weeds near pathways, gazebo, signpost, street lamp, main gate, monuments, dead trees.	Confirm which of these matter most for the DDA report and they can be added - most are feasible; the pipe in Clip 1 is a clear, high-contrast target.	Survey / Drone Cell

Generated from Smriti_Van_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 4 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.