

SMRITI VAN MAYUR VIHAR — PLANTS & TREES

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Smriti Van Mayur Vihar, Mayur Vihar (DDA)

Survey date: 19 May 2026, 16:54-17:35 IST (single-date baseline)

Category: Plants & Trees

CATEGORY SCORE				
Indicator	Mean	Min	Max	Rating
Plantation Health	77.3%	43.5%	93.2%	Good

SCENE COVERAGE (park-wide mean)			
Metric	Mean	Min	Max
Tree canopy	21.4%	1.1%	58.1%
Lawn cover	9.2%	0%	47.7%
Green cover	34.8%	1.9%	90.5%

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Tree Stem	3384	91.5	43.7	Good
Tree Canopy	1201	83.6	36.6	Good
Lawn / Grass	996	67.6	38	Fair
Shrub / Hedge	1679	69.3	17	Fair
Dry / Dead Vegetation	82	50.7	49	Poor

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
4	Lawns & tree belt	Shrub / Hedge	Critical	17.5	Trim and gap-fill; protect from material storage.
11	Lawns & tree belt	Shrub / Hedge	Critical	27.7	Trim and gap-fill; protect from material storage.
12	Lawns & tree belt	Shrub / Hedge	Critical	29.5	Trim and gap-fill; protect from material storage.
31	Waterlogged ground	Tree Canopy	High	38.1	Arboricultural check - protect root zones from compaction by site traffic.
33	Lawns & tree belt	Lawn / Grass	High	38.5	Aerate, feed and overseed once works traffic ceases.
34	Waterlogged ground	Tree Canopy	High	38.8	Arboricultural check - protect root zones from compaction by site traffic.
46	Waterlogged ground	Lawn / Grass	High	41.8	Aerate, feed and overseed once works traffic ceases.
52	Lawns & tree belt	Shrub / Hedge	High	43	Trim and gap-fill; protect from material storage.
55	Flooded planting bed	Shrub / Hedge	High	43.1	Trim and gap-fill; protect from material storage.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
64	Lawns & tree belt	Lawn / Grass	High	44.8	Aerate, feed and overseed once works traffic ceases.
67	Waterlogged ground	Shrub / Hedge	Medium	45.2	Trim and gap-fill; protect from material storage.
71	Waterlogged ground	Lawn / Grass	Medium	45.8	Aerate, feed and overseed once works traffic ceases.
78	Lawns & tree belt	Shrub / Hedge	Medium	46.6	Trim and gap-fill; protect from material storage.
80	Waterlogged ground	Lawn / Grass	Medium	47	Aerate, feed and overseed once works traffic ceases.
84	Flooded planting bed	Tree Canopy	Medium	47.3	Arboricultural check - protect root zones from compaction by site traffic.
83	Lawns & tree belt	Lawn / Grass	Medium	47.3	Aerate, feed and overseed once works traffic ceases.
85	Waterlogged ground	Lawn / Grass	Medium	47.4	Aerate, feed and overseed once works traffic ceases.
87	Waterlogged ground	Shrub / Hedge	Medium	47.9	Trim and gap-fill; protect from material storage.
107	Waterlogged ground	Dry / Dead Vegetation	Medium	49.2	Clear dry and dead material from the works margin.
112	Lawns & tree belt	Lawn / Grass	Medium	49.4	Aerate, feed and overseed once works traffic ceases.
120	Waterlogged ground	Shrub / Hedge	Medium	49.9	Trim and gap-fill; protect from material storage.
123	Waterlogged ground	Dry / Dead Vegetation	Medium	50	Clear dry and dead material from the works margin.
125	Waterlogged ground	Dry / Dead Vegetation	Medium	50.2	Clear dry and dead material from the works margin.
129	Waterlogged ground	Dry / Dead Vegetation	Medium	50.5	Clear dry and dead material from the works margin.
132	Waterlogged ground	Lawn / Grass	Medium	50.7	Aerate, feed and overseed once works traffic ceases.
135	Waterlogged ground	Dry / Dead Vegetation	Medium	50.9	Clear dry and dead material from the works margin.
136	Waterlogged ground	Dry / Dead Vegetation	Medium	50.9	Clear dry and dead material from the works margin.
137	Waterlogged ground	Dry / Dead Vegetation	Medium	51	Clear dry and dead material from the works margin.
139	Lawns & tree belt	Lawn / Grass	Medium	51.1	Aerate, feed and overseed once works traffic ceases.
140	Waterlogged ground	Dry / Dead Vegetation	Medium	51.2	Clear dry and dead material from the works margin.
141	Waterlogged ground	Dry / Dead Vegetation	Medium	51.4	Clear dry and dead material from the works margin.
142	Flooded planting bed	Shrub / Hedge	Medium	51.5	Trim and gap-fill; protect from material storage.
143	Waterlogged ground	Shrub / Hedge	Medium	51.6	Trim and gap-fill; protect from material storage.
152	Waterlogged ground	Shrub / Hedge	Medium	53	Trim and gap-fill; protect from material storage.
154	Flooded planting bed	Lawn / Grass	Medium	53.3	Aerate, feed and overseed once works traffic ceases.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
164	Waterlogged ground	Shrub / Hedge	Medium	54.1	Trim and gap-fill; protect from material storage.
186	Flooded planting bed	Shrub / Hedge	Medium	55.3	Trim and gap-fill; protect from material storage.
189	Children's play area	Tree Stem	Medium	55.4	Field verification required.
190	Children's play area	Shrub / Hedge	Medium	56.1	Trim and gap-fill; protect from material storage.
191	Waterlogged ground	Lawn / Grass	Medium	56.2	Aerate, feed and overseed once works traffic ceases.

Showing the worst 40 of 60 tracked instances in this category.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
2	High	Ground cover has failed across the three used zones - bare and dry ground at 23-30% of frame, lawn under 6%.	Reinstate ground cover after drainage is fixed: decompact, regrade to fall away from the beds, then re-turf and establish an watering regime matched to the corrected drainage.	Horticulture Division
7	Low	The lawn and tree belt zone is in good condition - roughly 75% green cover and a cleanliness score of 83.	Maintain the current regime there and extend the same standard to the other three zones.	Horticulture Division

Generated from Smriti_Van_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 4 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.