

VASANT UDYAN — IRRIGATION STATUS

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Vasant Udyan, Vasant Kunj (DDA)

Survey date: 18 May 2026, 15:03-15:07 IST (single-date baseline)

Category: Irrigation Status

CATEGORY SCORE					
Indicator		Mean	Min	Max	Rating
Irrigation Efficiency		55.2%	33.8%	83.1%	Poor

SCENE COVERAGE (park-wide mean)			
Metric		Mean	Max
Bare ground		26.7%	38.5%
Dry vegetation		0.6%	2.9%
Waterlogging		6.1%	15.3%

DETECTOR FINDINGS				
Detector class		Records	Mean cond. %	Condition
Waterlogging		315	47.5	Poor
Bare Ground Patch		606	42.4	Poor
Dry / Dead Vegetation		106	51.1	Poor

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
1	Children's play area	Bare Ground Patch	Critical	22.2	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
2	Children's play area	Bare Ground Patch	Critical	25	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
5	Pathways & tree belt	Bare Ground Patch	High	32.9	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
7	Pathways & tree belt	Bare Ground Patch	High	35.9	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
8	Children's play area	Bare Ground Patch	High	36	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
13	Children's play area	Bare Ground Patch	High	38.4	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
21	Children's play area	Bare Ground Patch	High	40.5	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
22	Children's play area	Bare Ground Patch	High	40.5	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
38	Children's play area	Waterlogging	High	44.6	Investigate drainage; standing water is a slip and mosquito-breeding risk.
40	Children's play area	Waterlogging	High	44.8	Investigate drainage; standing water is a slip and mosquito-breeding risk.
43	Children's play area	Bare Ground Patch	Medium	45.1	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
42	Pathways & tree belt	Bare Ground Patch	Medium	45.1	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
50	Children's play area	Waterlogging	Medium	46.2	Investigate drainage; standing water is a slip and mosquito-breeding risk.
51	Pathways & tree belt	Waterlogging	Medium	46.3	Investigate drainage; standing water is a slip and mosquito-breeding risk.
59	Children's play area	Waterlogging	Medium	48.1	Investigate drainage; standing water is a slip and mosquito-breeding risk.
60	Children's play area	Waterlogging	Medium	48.2	Investigate drainage; standing water is a slip and mosquito-breeding risk.
62	Children's play area	Waterlogging	Medium	48.7	Investigate drainage; standing water is a slip and mosquito-breeding risk.
63	Children's play area	Waterlogging	Medium	48.9	Investigate drainage; standing water is a slip and mosquito-breeding risk.
64	Children's play area	Waterlogging	Medium	49.2	Investigate drainage; standing water is a slip and mosquito-breeding risk.
66	Children's play area	Waterlogging	Medium	49.3	Investigate drainage; standing water is a slip and mosquito-breeding risk.
67	Children's play area	Waterlogging	Medium	49.5	Investigate drainage; standing water is a slip and mosquito-breeding risk.
68	Children's play area	Waterlogging	Medium	49.5	Investigate drainage; standing water is a slip and mosquito-breeding risk.
69	Children's play area	Waterlogging	Medium	49.5	Investigate drainage; standing water is a slip and mosquito-breeding risk.
71	Children's play area	Waterlogging	Medium	49.7	Investigate drainage; standing water is a slip and mosquito-breeding risk.
72	Children's play area	Waterlogging	Medium	49.7	Investigate drainage; standing water is a slip and mosquito-breeding risk.
70	Pathways & tree belt	Bare Ground Patch	Medium	49.7	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
73	Children's play area	Waterlogging	Medium	49.9	Investigate drainage; standing water is a slip and mosquito-breeding risk.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
74	Children's play area	Bare Ground Patch	Medium	50.3	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
76	Children's play area	Bare Ground Patch	Medium	50.3	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
77	Children's play area	Dry / Dead Vegetation	Medium	50.6	Clear dry and dead material; prune out deadwood and irrigate.
80	Children's play area	Bare Ground Patch	Medium	51.1	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
84	Pathways & tree belt	Dry / Dead Vegetation	Medium	51.2	Clear dry and dead material; prune out deadwood and irrigate.
85	Children's play area	Dry / Dead Vegetation	Medium	51.3	Clear dry and dead material; prune out deadwood and irrigate.
86	Children's play area	Dry / Dead Vegetation	Medium	51.4	Clear dry and dead material; prune out deadwood and irrigate.
88	Children's play area	Dry / Dead Vegetation	Medium	51.5	Clear dry and dead material; prune out deadwood and irrigate.
89	Pathways & tree belt	Dry / Dead Vegetation	Medium	51.5	Clear dry and dead material; prune out deadwood and irrigate.
90	Pathways & tree belt	Bare Ground Patch	Medium	51.6	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
92	Pathways & tree belt	Bare Ground Patch	Medium	51.9	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
94	Children's play area	Bare Ground Patch	Medium	52.8	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.
95	Children's play area	Bare Ground Patch	Medium	52.9	Decompact, top-dress and re-establish ground cover; review watering coverage for this zone.

Showing the worst 40 of 46 tracked instances in this category.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
1	Critical	The ground plane has failed in both zones - bare hard-packed earth at 30.5% and 21.2% of frame with lawn cover at 2.4% and 8.0%. watering scores 46.9 in the play area.	Reinstate ground cover as a programme, not a patch repair: decompact, regrade, re-turf and install watering that actually reaches the play area. Under play equipment, install a proper impact-absorbing surface rather than bare earth.	Horticulture / Engineering
6	Process	No class exists for: broken equipment, signboards, gazebo / pergola, streetlights, dustbins, boundary wall as distinct from kerb, or the waterway condition recorded on site.	Confirm which matter most for the DDA report. 'Broken' is genuinely hard from imagery; a low-altitude pass over the play equipment would serve better than a detector.	Survey / Drone Cell
7	Process	The site record mentions a waterway that is not clear and a gazebo, neither substantially covered by these two clips.	Fly the waterway and the gazebo area to capture that evidence.	Survey / Drone Cell

Generated from Vasant_Udyan_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 2 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.