

Mods(marked in green):

1. The holes have to be M3 clearance holes.