

KAFAOGLU METAL PLASTIK MAKINE SAN. VE TIC. A.S.

OCCUPATIONAL HEALTH & SAFETY COMPLIANCE POLICY MANUAL

Factory Operations — Production Floor Regulations

Document No.	KMP-OHS-POL-001
Effective Date	01 November 2022
Classification	Internal — Mandatory Compliance
Issuing Authority	EHS Department / Occupational Safety Expert
Applies To	All production floor personnel, contractors, and visitors

CONTROLLED DOCUMENT — DO NOT DUPLICATE WITHOUT AUTHORIZATION

SECTION 1 — PURPOSE, SCOPE, AND BACKGROUND

1.1 Purpose

This Occupational Health and Safety Compliance Policy Manual (hereinafter "the Manual") establishes the mandatory behavioral standards governing all activities conducted within the production facilities of Kafaoglu Metal Plastik Makine San. ve Tic. A.S. (hereinafter "the Company"). The Manual defines which observable behaviors on the production floor are classified as safe or unsafe, and describes the monitoring and alert mechanisms in place to detect and respond to unsafe behaviors in real time.

Unsafe behaviors are a leading cause of occupational accidents. Globally, it is estimated that approximately 2.3 million occupational accidents and diseases occur each year, resulting in around 0.3 million deaths. The economic costs of work-related injuries and illnesses are estimated at between 1.8% and 6.0% of GDP across countries, with an average of 4% according to the International Labour Organization (ILO). The Company is committed to minimizing the contribution of unsafe behavior to these figures within its own operations.

Despite regular safety inspections and ongoing preventive measures, accidents continue to occur as a result of breaches of occupational health and safety protocols. Human error cannot be completely eliminated through inspection alone. This Manual therefore sets out the behavioral standards and automated monitoring measures that complement inspection activities.

1.2 Scope of Application

This Manual applies to all personnel operating on the production floor, including full-time and temporary employees, subcontractors, maintenance personnel, and visitors. It defines four specific behavioral domains — pedestrian movement, equipment intervention, electrical panel management, and forklift load management — within which safe and unsafe behaviors have been identified in consultation with the Company's occupational safety expert.

1.3 Monitoring and Enforcement

The Company has installed an automated real-time behavior detection and warning system on the production floor. This system continuously monitors live video feeds from IP cameras installed throughout the facility. When an unsafe behavior is detected, the system immediately issues both audible and visual warnings in the area where the behavior is occurring, and automatically logs the event for reporting. The provisions of this Manual define the behaviors that trigger these automated responses.

SECTION 2 — DEFINITIONS AND CLASSIFICATION OF BEHAVIORS

2.1 Behavioral Classification Framework

All observable behaviors on the production floor are classified into two categories: Safe Behaviors and Unsafe Behaviors. For each of the four operational domains covered by this Manual, a specific safe behavior and a specific unsafe behavior have been defined. These definitions form the basis for the automated monitoring system's detection logic and for the alert and reporting procedures described in Section 7.

2.2 Glossary of Terms

Term	Definition
Safe Behavior	An observable action that conforms to the operational standards defined in this Manual for the relevant behavioral domain. Safe behaviors are the expected norm and do not trigger monitoring alerts.
Unsafe Behavior	An observable action that deviates from the operational standards defined in this Manual and creates a risk of injury or operational harm. Unsafe behaviors trigger the automated alert and reporting system described in Section 7.
Designated Safe Walkway	The pedestrian pathway within the production floor that is delineated by green painted floor markings. Personnel on foot are required to remain within these green-marked boundaries at all times during production operations.
Safe Walkway Violation	The unsafe behavior of moving outside the boundaries of the Designated Safe Walkway. Defined as the opposite of the Safe Walkway behavior.
Authorized Intervention	The safe behavior of interacting with or working on production equipment while wearing the designated green safety vest, indicating that the individual has been cleared to perform that activity. The green vest is the observable indicator of authorization.
Unauthorized Intervention	The unsafe behavior of interacting with or working on production equipment while not wearing the designated green safety vest, or while not wearing the required safety equipment. Defined as the opposite of Authorized Intervention. This includes situations where personnel intervene in situations at work sites without authorization and without appropriate safety equipment.
Closed Panel Cover	The safe condition in which the protective cover of an electrical panel connected to a machine is fully closed. This is the required state during normal production operations.
Opened Panel Cover	The unsafe condition of leaving or forgetting a panel cover in the open position. Defined as the opposite of the Closed Panel Cover condition.
Safe Carrying	The safe behavior of operating a forklift while carrying two (2) or fewer standardized blocks as a single load.
Carrying Overload with Forklift	The unsafe behavior of operating a forklift while carrying three (3) or more standardized blocks as a single load. Defined as the opposite of Safe Carrying.
Green Safety Vest (Authorized)	The specific green-colored safety vest that indicates a personnel member is authorized to perform an intervention activity. Wearing this vest is the primary observable indicator distinguishing Authorized from Unauthorized Intervention.

Term	Definition
Red-Black Safety Vest (General)	A safety vest of red and black coloring, worn by general production personnel who are not cleared for direct equipment intervention. Personnel in a red-black vest interacting with equipment are classified as performing an Unauthorized Intervention.
Occupational Safety Expert	The qualified safety professional based at the Company's facility who is responsible for verifying behavioral classifications, supervising ground-truth assessment of compliance events, and overseeing occupational safety matters.

SECTION 3 — PEDESTRIAN WALKWAY REGULATIONS

3.1 Hazard Context

The production floor involves the simultaneous presence of operating machinery, moving forklifts, and on-foot personnel. Separating pedestrian movement from machinery and vehicle activity is a fundamental safety measure. The Designated Safe Walkway provides a defined, physically marked route for all foot traffic on the production floor.

3.2 Walkway Markings

The Designated Safe Walkway is physically marked on the production floor using green painted lines. These green markings define the boundary of the permitted pedestrian zone. The floor of the facility also features yellow painted lines that further delineate zones within the workspace. Personnel on foot must remain within the green-marked pathway boundaries.

NOTE

The green-marked Designated Safe Walkway boundaries are visible in the facility's surveillance camera views and form the primary reference boundary for the automated walkway compliance detection system.

3.3 Behavioral Standards

3.3.1 Required Behavior — Safe Walkway (Compliant)

Safe Walkway is defined as movement along the production floor that remains within the boundaries of the green-marked Designated Safe Walkway. This is the required and expected behavior for all personnel moving through the production facility on foot.

3.3.2 Non-Compliant Behavior — Safe Walkway Violation

A Safe Walkway Violation is defined as movement or presence outside the boundaries of the green-marked Designated Safe Walkway. This is the most frequently occurring unsafe behavior documented at this facility. A Safe Walkway Violation is detected when a person's position in the video frame places them beyond the green walkway boundaries and into an area designated for machinery or vehicle operation.

WARNING

The Safe Walkway Violation is the highest-frequency unsafe behavior recorded at this facility. The frequency of this behavior reflects a tendency among personnel to treat minor deviations from the walkway as inconsequential. Any deviation from the green-marked boundaries places the individual in proximity to forklift and machinery hazards and will be treated as an unsafe behavior event requiring immediate response.

SECTION 4 — EQUIPMENT AND MACHINERY INTERVENTION

4.1 Hazard Context

Interaction with production equipment and machinery by personnel who are not cleared for the relevant task creates risk of injury to the intervening individual and to others in the area, and may disrupt production processes. Authorized personnel are visually distinguished from unauthorized personnel by the safety vest they wear. This vest-based visual identification system is the primary mechanism by which intervention compliance is assessed and monitored.

4.2 Vest Identification System

The facility operates a safety vest color system to indicate the authorization status of personnel interacting with equipment:

- Green safety vest: worn by personnel who have been authorized to perform an intervention or maintenance activity at a specific piece of equipment. The green vest is the observable indicator of authorization.
- Red-black safety vest: worn by general production personnel who are not cleared for direct equipment intervention. This is the standard vest for production floor personnel not performing an authorized task.

The color of the safety vest worn by a person interacting with equipment is the primary observable criterion for classifying the behavior as Authorized or Unauthorized Intervention.

4.3 Behavioral Standards

4.3.1 Required Behavior — Authorized Intervention (Compliant)

An Authorized Intervention is defined as an interaction with or working on production equipment performed by a person who is wearing the designated green safety vest and the required safety equipment for the task. The green vest indicates that the individual has been cleared to perform the activity in question. This is the required and expected behavior for all equipment interaction on the production floor.

4.3.2 Non-Compliant Behavior — Unauthorized Intervention

An Unauthorized Intervention is defined as any of the following observable situations:

- A person interacting with or adjusting production equipment while wearing a red-black vest or any vest other than the designated green authorization vest.
- A person interacting with or adjusting production equipment while not wearing the required safety equipment for the task.
- A person intervening in a work situation at a production site without the observable indicators of authorization (i.e., the green vest).

CRITICAL SAFETY NOTICE

The green safety vest is the primary and most readily observable indicator of authorization status. Any person seen interacting with equipment who is not wearing the green vest must be assumed to be performing an Unauthorized Intervention. This classification applies regardless of the person's stated intent or role, since the vest system exists precisely to make authorization status unambiguous to observers and to the automated monitoring system.

SECTION 5 — ELECTRICAL PANEL COVER MANAGEMENT

5.1 Hazard Context

Electrical panels connected to production machinery are present throughout the facility. The covers of these panels serve as a protective barrier between personnel and the electrical components of the connected equipment. Leaving panel covers open or forgetting to close them after accessing the panel is an identified unsafe behavior at this facility.

5.2 Behavioral Standards

5.2.1 Required Behavior — Closed Panel Cover (Compliant)

Closed Panel Cover is defined as the condition in which the cover of an electrical panel connected to a production machine is fully closed. This is the required and expected state for all electrical panels during production operations.

5.2.2 Non-Compliant Condition — Opened Panel Cover (Unsafe)

Opened Panel Cover is defined as the condition in which the cover of an electrical panel connected to a production machine has been left in the open position. This includes both the deliberate leaving of a panel cover open and the inadvertent forgetting to close a panel cover after accessing it.

An Opened Panel Cover is detected when the surveillance system observes a panel in the open-cover state during production operations. The condition is an unsafe behavior event regardless of how long the panel has been open or whether personnel are in the immediate vicinity at the moment of detection.

WARNING

Leaving a panel cover open — even when doing so feels like a minor or temporary oversight — is classified as an unsafe behavior under this Manual. The automated detection system monitors panel cover status continuously and will generate an alert whenever an open-cover condition is observed.

SECTION 6 — FORKLIFT LOAD MANAGEMENT

6.1 Hazard Context

Forklifts operate within the production floor to carry materials between workstations. Carrying loads that exceed the defined safe limit creates risks associated with vehicle instability. The safe carrying limit for this facility is defined in terms of the number of standardized block units carried in a single forklift load operation.

6.2 Load Capacity Definition

For all forklift operations within this facility involving standardized block materials, the following load thresholds apply:

Load Configuration	Number of Blocks Carried	Compliance Status
Safe Carrying	2 blocks or fewer	COMPLIANT — Required behavior
Carrying Overload with Forklift	3 blocks or more	NON-COMPLIANT — Unsafe behavior

These thresholds apply to the standardized blocks used in this facility's production workflow. The number of blocks visible on the forklift forks during travel is the observable criterion used by the automated detection system to classify the load as safe or overloaded.

6.3 Behavioral Standards

6.3.1 Required Behavior — Safe Carrying (Compliant)

Safe Carrying is defined as operating a forklift while carrying two (2) or fewer standardized blocks in a single load. This is the required and expected behavior for all forklift load operations within the facility.

6.3.2 Non-Compliant Behavior — Carrying Overload with Forklift

Carrying Overload with Forklift is defined as operating a forklift while carrying three (3) or more standardized blocks in a single load. Three or more blocks on the forks during any phase of a load operation — including travel, maneuvering, and loading/unloading — constitutes an unsafe behavior event.

**CRITICAL
SAFETY
NOTICE**

The block count threshold is unambiguous: two blocks or fewer is safe; three blocks or more is an overload. Any observed forklift load of three or more standardized blocks will be treated as a Carrying Overload with Forklift event and will trigger an immediate alert.

SECTION 7 — SURVEILLANCE, MONITORING, AND ALERT SYSTEM

7.1 Camera Infrastructure

The production floor is monitored by two IP cameras (brand: UNV, model: IPC2122CR3-PF40-A) providing continuous Full HD (1920×1080) video coverage of the active production zones. The cameras are positioned to provide views of the areas relevant to the four behavioral domains defined in this Manual. Video feeds are transmitted in real time to the facility's monitoring infrastructure.

Employees working in the monitored areas have been informed of the surveillance system and a consent form for the protection and use of personal data has been obtained from all personnel whose images are captured in the recorded footage.

7.2 Automated Behavior Detection

An automated unsafe behavior detection system continuously processes the live camera feeds. This system is capable of identifying the following unsafe behavior conditions in real time:

- Safe Walkway Violation — a person moving or present outside the green-marked walkway boundaries (Section 3).
- Unauthorized Intervention — a person interacting with production equipment without wearing the green authorization vest, or without required safety equipment (Section 4).
- Opened Panel Cover — an electrical panel connected to a production machine observed in the open-cover state during production operations (Section 5).
- Carrying Overload with Forklift — a forklift observed carrying three or more standardized blocks in a single load (Section 6).

7.3 Monitoring Interface and Reporting

The detection and alert system is managed through a dedicated graphical user interface (GUI) installed at the facility. This interface provides the following capabilities:

- Live view of the camera feeds covering the production floor.
- Access to the automated event reports generated when unsafe behaviors are detected. Reports are produced in text document format and record the event type, zone, and timestamp for each detection.

The event reports generated by the system constitute the primary compliance record for the facility. These reports document each detected unsafe behavior event and are used by the occupational safety expert to assess behavioral trends and the effectiveness of corrective measures over time.

SECTION 8 — QUICK REFERENCE: BEHAVIOR CLASSIFICATION SUMMARY

The table below provides a complete reference for all eight behavior classes defined in this Manual — four unsafe and four safe — with their observable identifying characteristics and the policy section governing each.

Class ID	Behavior Domain	Unsafe Behavior	Safe Behavior (Compliant Pair)	Observable Indicator of Unsafe
0	Pedestrian Movement	Safe Walkway Violation	Safe Walkway	Person outside green floor markings
1	Equipment Interaction	Unauthorized Intervention	Authorized Intervention	Person interacting with equipment without green vest or without required safety equipment
2	Electrical Safety	Opened Panel Cover	Closed Panel Cover	Panel cover in open position during production operations
3	Forklift Load	Carrying Overload with Forklift	Safe Carrying	3 or more blocks on forklift forks

IMPORTANT

Each unsafe behavior has a directly corresponding safe behavior. The automated detection system monitors for the four unsafe categories. The safe categories represent the required default state — no alert is generated when the safe behavior is observed.