
Tracking, sampled safety, effort and computing trade-offs
B0_PI
B4_mhe
B1_co
Mean thermal exceedance integral (K h)
0.0
0.2
0.4
0.6
0.8
0.09
0.10
0.11
0.12
0.13
0.14
Mean IAE
log10 decision ms; marker area scales with effort
0.5
0.0
−0.5
−1.0
−1.5