

DoC/DGL Report

November 13-19 2017 PFG Meeting


Tanvi Wamorkar, Andrea Beschi

Overview of the Week

- p-p reference runs at 5 TeV with long fills >24h
 - Fill 6384 6398
 - ~300/pb recorded luminosity


Smooth week for ECAL and ES


 Good performance! only ~0.17/pb lost lumi due to ECAL



Day by day: Monday


- Before the 1800b fill
 - ES conditions switched to HG
 - ES online pedestals switched to HG
 - cDAQ shifter informed to manually switch the ES run key to HighGain-TCDS
- Run 306580 ELOG
 - cDQM shifter called to inform about red clusters in EE-06 Emulator quality summary plot
 - From the Emulation plot it was found that there were some towers with no emulation
 - No action needed
 - Instructions for this already exist in long term DQM instructions





Day by day: Monday (2)

Run 306584 ELOG




- Red clusters seen in Laser 3 (Blue) quality summary plot
- Laser expert was contacted
 - Around 18:00h the blue laser DP2-1 stopped automatically, error on laser was "Error Low Flow", but nothing was found bad. (Fake error message?)
 - Spare blue laser DP2-2 was put into use
 - ECAL DAQ expert made a change in the calibration sequence to load the spare blue laser and this was followed by RR of ECAL
 - The problem still persisted and it was found that change in calibration sequence was not needed and the original sequence was restored
 - Data still good for physics

Day by day: <u>Tuesday</u>

- 1800b was dumped around 10:30 h
- ES conditions were switched back from HG to LG
- ECAL in local to take pedestals and to update laser transparency corrections
 - ECAL pedestals run: 306606
 - ECAL test pulses run : 306612
 - Runs were reprocessed with full statistics and are available on ECAL private DQM and on ECAL Cond DB
- Pedestals measurements also done for ES
- ECAL/ES was back in global starting Run 306621
- Smooth running for the rest of the day


Day by day: Wednesday

- Run 306670
 - ECAL + ES were put in Local for GEM's high rate tests
 - During time in local: code modification done for two TCC boards: TCC18 and TCC88. The code update was first tested in miniDAQ and then deployed in Global when ECAL was put back in global during Run 306696
- Run 306702 (circulating; beams in adjust)
 - ECAL failed a number of times while trying to configure ECAL was not able to communicate with a crate
 - Reconfigure was successful on the 3rd try
- Immediately after this integrity errors were seen in EB+08
 - Errors not seen in the "by Lumisection" plot
 - No action needed
- Run 306705 <u>ELOG</u>
 - cDQM shifter called to report about Integrity errors in EB-06
 - Integrity errors only appeared for some isolated towers and faded away after a while
 - No action was needed




Day by day: Wednesday (2)


- Run 306706 (Cosmics): <u>ELOG</u>
 - cDQM shifter called to inform about red clusters in EE-04 L3 laser quality summary plot
 - Laser expert contacted
 - No problem was found with the laser and no action was needed



Day by day: Thursday

- Run 306709 (Collisions): <u>ELOG</u>
 - cDQM shifter called to inform about red clusters in EB +03 integrity quality summary plot
 - No errors seen in the "by lumi" plot
 - No action needed





- Beam was dumped ~14:10h
 - Run 306711 first run (cosmic) after beam dump
 - Since the interfill was only ~1 hour, this was not enough time to do SPR measurement
 - Laser transparency corrections were updated in DB

Day by day: Friday

Quiet day

Day by day: Saturday

- Beam dump occurred at 12:02h
 - Laser transparency correction updated by Jean
 - Run 306791 : ECAL was put in global following a RR

Day by day: Sunday

Quiet day for ECAL