

U.S. Coast Guard Safety Alert



Marine Safety, Security and Environmental Protection

June 22, 2005 Washington, DC Alert 4-05

Personal Flotation Devices - Incorrect CO₂ Cylinder Installation / False Positive Service Indicators

Recently the U.S. Coast Guard has become aware of a potential problem when installing CO₂ cylinders that have bayonet tips in inflatable personal flotation devices (PFDs or life jackets). If a cylinder is not properly installed, the PFD will not inflate with CO₂. The problem may affect several thousand PFDs, but the Coast Guard is only aware of one incident to date.

Some Mustang, Protexion, and Stearns/SOSpenders PFDs using Halkey-Roberts' inflators can indicate a green "Ready" status when the CO₂ cylinder is not properly installed. This false positive green indication occurs when the cylinder-bayonet assembly is inserted in the inflator, not turned, and the cylinder is not ejected.

Cylinders with bayonet tips are designed to be pushed in and turned $1/8^{th}$ turn clockwise to a full stop to secure the cylinder. When the cylinder is not turned to secure it in place, the PFD will not inflate with CO_2 . The PFD may still be inflated orally. If the CO_2 cylinder is not turned, the mechanism is supposed to eject it. In some production units a false positive green indication can be achieved by simply pushing the cylinder into the mechanism without turning it $1/8^{th}$ turn to a full stop. According to the consumer report, a user was led to believe the cylinder-bayonet was properly engaged without turning it due to the firm seating of the cylinder-bayonet, which also prevented the cylinder-bayonet from ejecting as designed.

Consumers should check the model number of the PFD (located on the manufacturer's label) to see if your PFD is affected. The models numbers are:

Manufacturer	PFD Model #	Contact Number
Mustang Survival	MC1900 Automatic	1-800-526-0532 (USA)
Customer	MC1900HR Automatic	1-800-661-6181 (CAN)
Service	w/ Harness	www.mustangsurvival.com
3870 Mustang	MD0100 LIFT Vest	
Way	Manual	
Bellingham, WA	MD0200 LIFT Vest	
98226	Automatic	
USA	MD3081 Manual	
	MD3082 Manual with	
	Harness	
	MD3083 Automatic	
	MD3084 Automatic w/	
	Harness	
	All colors and Styles	



U.S. Coast Guard Safety Alert



Marine Safety, Security and Environmental Protection

	PFD Model #	Contact Number
Manufacturer		
Protexion Products Inc.	NIV3000, Manual	1-800-268-3112
643 Speedvale	NIV3500, Manual with Harness	www.nautilusbyprotexion.com customerservice@protexionproducts.com
Ave W	NIV4000, Automatic	<u> </u>
Guelph Ontario	NIV4500, Automatic	
N1K 1E6	with Harness	
CANADA		
Stearns Inc.	38MLNG, Manual	1-800-328-3208 EXT 1
1100 Stearns	38MHRN, Manual w/	www.stearnsinc.com
Drive	Harness	
Sauk Rapids, MN	24MSPT, Manual	
56379 (also	38MREG, Manual 38MBP, Manual	
SOSpenders)	38ASSTD, Automatic	
	38ASHAR, Automatic	
	w/ Harness	
	38ASPRO, Automatic	
	38CHR, Automatic and	
	Manual	
	1469, Automatic	
	1473, Automatic with Harness	

Updated cylinder installation instructions are on the home pages of manufacturers' websites and at the Coast Guard website listed below. Review and follow the instructions. Check your device to ensure that the inserted CO₂ cylinder-bayonet has been fully turned clockwise prior to use.

If your PFD inflator does not eject an unturned cylinder-bayonet, contact the PFD manufacturer for servicing.

View the following documents for updated rearming instructions:

Manual inflator rearming – http://www.uscg.mil/hq/g-m/moa/docs/co2man.pdf Automatic inflator rearming - http://www.uscg.mil/hq/g-m/moa/docs/co2auto.pdf

For other PFD related recalls and alerts access - http://www.uscg.mil/hq/g-m/mse4/recall.htm For additional safety alerts access - http://marinesafetyalerts.us

This safety alert is provided for informational purposes only and does not relieve any existing domestic or international safety, operational, or material requirement.