1. Fix 5V buck bug
2. 12V buck改成一直使能
3. Fix LCD bias bug
4. 副屏背光微调
5. ip2368电路微调,增加供电脚电容
6. 修改电池接口定义
7. 去掉rk3399端的vbat sns

REV A

V1.1

V2.0

V2.1

PD Keyboard evaluate version

1. 修改键盘主控方案为CH582M 2. STM32驱动屏幕

Official version



















