	图标	命令	快捷键	命令说明
39	++1	DIMLINEAR	DLI	两点标注
40	+	DIMCONTINUE	DCO	连续标注
41	ĪĪ	DIMBASELINE	DBA	基线标注
42	Ka	DIMALIGNED	DAL	斜点标注
43	8	DIMRADIUS	DRA	半径标注
44	0	DIMDIAMETER	DDI	直径标注
45	4	DIMANGULAR	DAN	角度标注
46	O I	TOLERANCE	TOL	公差
47	+	DIMCENTER	DCE	圆心标注
48	1	QLEADER	LE	引线标注
49	+	QDIM		快速标注
50	<a< td=""><td>DIMTEDIT</td><td></td><td>标</td></a<>	DIMTEDIT		标
51	\triangle	DIMEDIT		注编辑
52	A	DIMTEDIT		
53	料	DIMSTYLE		
54	₽,	DIMSTYLE	D	标注设置
55		HATCHEDIT	HE	编辑填充
56	_2	PEDIT	PE	编辑多义线