大型部品自动检查机

2021/11/26

上海索広映像有限公司

SSVE (Shanghai Suoguang Visual Products Co.,Ltd.)

检测项目内容:



主要检测项目:


1.外径寸法: OUTLINE DIMENSION长宽尺寸,变形 ---优先

2.混料防止:同一幅模具的部品,不同镶块检测 *同一部品上的洞孔不同

3.子部品的缺失检测


4.外观检查 (熔接线, 色差, BURR...) ---以后再检讨

<Measurement places>



OUTLINE DIMENSION






<Measurement method>

- 1. Prepare sample as below.
 - * Passing more than 1hour after injection
 - * Aging more than 30min at normal condition (Temp:15~25℃ / Humi:50~70%)
- 2. Put sample in condition core surface up on flat table.
- 3. Put some weight like the left figure.
- 4. Measure outside dimension by caliper.

Weight position is tentative.

<Measurement places>




55" 外形尺寸1229.4±0.6mm*707.8±0.4mm 85" 外形尺寸1278.8±0.8mm*1073.9±0.6mm

*治具检查精度由治具供应商定义

设计指示的测量方法

WARPING CHECK (1)






<Measurement method>

- 1. Prepare sample as below.
 - * Passing more than 1hour after injection
 - * Aging more than 30min at normal condition (Temp:15~25℃ / Humi:50~70%)
- 2. Put sample in condition core surface up on flat table
- 3. Put some weight like the left figure.
- 4. Measure the gap between sample and thread or wire by scale.


Weight position is tentative.



Warping变形量

WARPING CHECK (2)







<Measurement method>

- 1. Prepare sample as below.
 - * Passing more than 1hour after injection
 - * Aging more than 30min at normal condition (Temp:15~25℃ / Humi:50~70%)
- 2. Put sample in condition core surface up on flat table
- 3. Measure the gap between sample and thread or wire by scale.

<Measurement places>

: Measurement points








*Warping


= Measurement value - Spacer height





FINISHING CHECK





检测子部品缺失




Frequency : 100% visual & finger inspection after assembly

By whom : Operator


Specification: No missing and floating of catcher

Checking places : Refer to following

<Checking places>



3L: 18 places




4L: 19 places





Confirm catcher is NOT popped-out by pushing from core side



Approx. 3kgf (Use Small cover 100% check)

要求说明



- 1) 该检测治具兼容4款后盖产品(55"~85")的尺寸检查,生产节拍低于30S/台,最终提供给索广的部品供应商生产线使用。
- 2)部品的重量是85 ": 7700g, 55": 3100g, 部品的公差要求±0.6mm (移动平台, 校验标准件, Sensor)
- 3)治具的测量方式需要符合设计指示的测量方法如下图:
- ①放置在平板上 ②部品固定位置上需压块防止变形),放置压块请考虑使用液压系统,高度不在一个平面上
- 4)测定结果记录保存和可导出(部品上有QR条形码)
- 5) 治具流出的检验容错率为0, 索广会提前提供实物样品做验证。
- 6) 治具完成前的检证, 进度管理, 问题分析全部由治具厂家对应完成。

EoF