

Institute of Engineering Geodesy



Kinematic Measurement Systems Summer 2019

Lab 1 + 2

1

Laboratories 1+2: Dates+Structure

Room Time Date Group Preparation Tuesday All Students 24.01 11:30-13:00 16.04.2019 CIP-Pool IIGS Tuesday Group 1+2 11:30-13:00 23.04.2019 (6th Floor) Lab 1 Tuesday CIP-Pool IIGS Group 3+4 14:00-15:30 23.04.2019 (6th Floor) Tuesday CIP-Pool IIGS Group 1+2 11:30-13:00 30.04.2019 (6th Floor) Lab 2 Tuesday CIP-Pool IIGS Group 3+4 15:45-17:15 30.04.2019 (6th Floor)

Laboratories 1+2: Dates+Structure

Please choose your group!

- List is going around right now
- List will also put up on the IIGS Blackboard (6th floor, right hand side of the elevator)
- Once you've chosen a group, you have to stay in until lab 2 ends
- Dates and times can be found in ILIAS

Laboratories 1+2: Dates+Structure

The Labs are mandatory!

- You have to participate in all Labs
- They are precondition to take part in the final exam
- There is a guideline with rules for the labs and elaborations at IIGS, which you could find also in ILIAS


Programming of Robot Tachymeters

Principles

Content

- 1 Hardware of robot tachymeter
- 2 Serial interface RS 232C/ V24
- 3 Communication
- 4 Control commands (Leica GeoCom)
- 5 Contents Lab 1
- 6 Contents Lab 2

1. Hardware of robot tachymeter



UART: Universal Asynchronous Receiver/Transmitter

2. Serial interface RS 232 C / V24

- Standardized communications channel
- Transmission protocol fixes the communication parameters:
- Transfer rate in Baud = Bits/sec.
- Number of data bits und stop bits
- Parity check yes/no
- Interface uses handshakes to secure the communication
- At a transfer rate of 19200 Baud it's possible to transfer about 1700 ASCII characters/per second.

3. Communication

3.1 The demands for communication

- Control commands of the tachymeter have to be known (manufacturers' instructions)
- The interface has to be requested permanent ("automodus", no need for action)




- The PC must have a serial interface
- The use of any programming language is possible
- The interface has to be adressed within the program
 - Control commands have to be transferred to the tachymeter
 - The response of the tachymeter has to be processed.



3. Communication

3.2 Operation of communication



4. Control commands (Leica GeoCom for TCRP1201,TS30)

Command	Response	Meaning
%R1Q,9028:0 <cr></cr>	%R1P,0,0:0	Change face (I in II)
%R1Q,2008:1,1 <cr></cr>	%R1P,0,0:0	New measurement.
%R1Q,2108:0,0 <cr></cr>	%R1P,0,0:1284,5.7175979871, 1.561920067, 1.81901	Get the data Hz-angle [rad] V-angle [rad] slope distance [m]
%R1Q,2006:1 <cr></cr>		Compensator on

Communication parameters: transfer rate 19200 Baut, no parity, 8 bit, 1 stop bit

Task: Steering of the robot tachymeter

In this Lab functions should be created to establish the communication between the PC and the tachymeter to initiate the measurements using the graphical programming language "LabView".

Following functions are needed:

- Initialising
- Steering (e.g. change face, new measurement, readout the data)
- Storage into file


For steering commands 'write_and_wait_for_Ack.vi' is needed. This function will be provided → check at ILIAS!

Task: Steering of the robot tachymeter

In preparation of Lab 1 I would recommend you to watch some introductory YouTube Tutorials about programming in LabVIEW. For example the first few Videos of the Playlist "Getting Started with LabVIEW" by YouTube Channel "LabVIEW"

https://www.youtube.com/watch?v=ZHNIKyYzrPE&list=PLB968815D7BB78F9C

write_and_wait_for_Ack.vi'




Task: Programming the robot tachymeter

Here, the measured data should be processed. The main focus is to program a free stationing for the tachymeter using the Helmert Transformation and determine the coordinates of new object points, using the measured polar elements.

Following functions are needed:


- Readout of the measured data
- Reduction of slope distances
- Computation of local coordinates
- CoordinateTransformation from local to global reference system
- Coordinates determination of new object points in global system
- Data storage to file


Free Stationing - Principle



Workflow

Static positioning





- Contents of lab 1
- Contents of lab 2



Thank you!



M.Sc. Urs Basalla

e-mail urs.basalla@iigs.uni-stuttgart.de

phone +49 (0) 711 685-84058

www. iigs.uni-stuttgart.de

University of Stuttgart Institute of Engineering Geodesy Geschwister-Scholl-Straße 24 D, 70174 Stuttgart

Office: 6.345