

Delivery Index - Case T2R1NOCEILING

Case summary: NEGATIVE RESULT - best-effort design L passes ED/SEI100/lowT; 4C plating and SEI500 infeasible in the admissible space.

#	VBF number	Deliverable	Status
1	VBF-T2R1NOCEILING-DS-001	Design specification	Complete
2	VBF-T2R1NOCEILING-BOM-002	Bill of materials	Complete
3	VBF-T2R1NOCEILING-DSH-003	Datasheet	Complete
4	VBF-T2R1NOCEILING-CALC-004	Energy-density calculation + comparison	Complete
5	VBF-T2R1NOCEILING-DVPR-005	Design verification plan & report	Complete
6	VBF-T2R1NOCEILING-DFMEA-006	Design FMEA	Complete
7	VBF-T2R1NOCEILING-IDX-007	This index	Complete
8	VBF-T2R1NOCEILING-RPT-008	HTML report (report.html)	Complete