
Questions

- 1. What is the total number of cycles for running "all" trace (ZERO instruction included)?

 There are 13 cycles (including the ZERO instruction) for running "all" trace.
- 2. How many r-type instructions does this program ("all") have? There are 2 r-type instructions in "all".
- 3. What is the IPC of this processor (for "all" trace)?

 The IPC of "all" is 1.

Datapath & Controller



Table

Instruction	Opcode	RegWrite	AluSrc	Branch	MemRe	MemWr	MemtoReg	Jump	ALUOp
R-type	0110011	1	0	0	0	0	0	0	10
I-type	0010011	1	1	0	0	0	0	0	10
lw	0000011	1	1	0	1	0	1	0	00
sw	0100011	0	1	0	0	1	0	0	00
blt	1100011	0	0	1	0	0	0	0	01
jalr	1100111	1	1	0	0	0	0	1	00