## Anet 3D Printer A6 assembly parts list

Item	Picture	Name	QTY	Check	Item	Picture	Name	QTY	Check
1-1		Main support plate	1		2-1		Mainboard	1	
1-2		Side support plate	2		2-2		12864 LCD Screen	1	
1-3	(_color to t.c_t)	Back plate	1		2-3		Hot bed fixed aluminum plate	1	
1-4		Front plate	1		2-4		220mm*220mm*3mm Hot bed	1	
1-5	Anet 3D PRINTER	Filament support plate	2		2-5		Plastic nippers	1	
1-6		Filament support plate connecting plate	1		2-6		5mm*160mm Screwdriver	1	

Item	Picture	Name	QTY	Check	Item	Picture	Name	QTY	Check
1-7	Inet	Mainboard baffle	1		2-7		Three parts below in this bag	1	
2-23		Guide rod 418mm 2pcs Guide rod 380mm 2pcs Guide rod 340mm 2pcs	6		2-7-1		Wire 70CM	1	
2-24		T type lead screw M8*318mm 2pcs Threaded rod M8*400mm 2pcs Threaded rod M8*150mm 1pcs	5		2-7-2	10	Z axis Limit switch A 20CM Y axis Limit switch B 70CM X axis Limit switch C 90CM	3	
2-25	and the second	Screw bag include below screws			2-7-3		Pillar washer M3*7 4pcs Pillar washer M3*15 4pcs	8	
2-25-1		M3*18 screw 44个			2-8		Three parts below in this bag	1	
2-25-2	a second	M3 Nut 58个	1		2-8-1		3mm*130mm Screwdriver	1	
2-25-3		M8 Nut 18个 M8 Spacer 12个	1		2-8-2		Hex wrench M1.5 Hex wrench M2 Hex wrench M2.5 Hex wrench M3	4	

Item	Picture	Name	QTY	Check	Item	Picture	Name	QTY	Check
2-25-4	d to the first district the firs	M4*8 screw 16个 M4*14 screw 4个	1		2-8-3	7	Open spanner	1	
2-25-5	\$ 16 km	M3*30 screw 12个	1		2-9		5015 Air blower	1	
2-25-6	0 01 mm 0 01 mm 0 01 mm	M3*12 screw 19个	1		2-10		Power line of hot bed	1	
2-25-7		M2*12 screw 6个 M3wing nut 4个 Spring 4个	1		2-11		Five parts below in this bag	1	
2-25-8		M3*6 screw 2个 M3*10 screw 2个 M3*25 screw 2个	1		2-11-1		Y axis belt fixation clamp	2	
3-1	**************************************	Left Z axis nut support	1		2-11-2	(8)	Guide rod back up plate	8	
3-2	8	Right Z axis nut support	1		2-11-3	E.	Y axis Limit switch fixed plate	1	

Item	Picture	Name	QTY	Check	Item	Picture	Name	QTY	Check
3-3		Extruder	1		2-11-4		Y axis motor support	1	
3-4		X axis motor	1		2-11-5	• •	X axis Limit switch fixed plate	1	
3-5		Y axis motor	1		2-12	O.M.S	Z axis motor support Plate	4	
3-6		Z axis motor	2		2-13		Screen baffle plate	1	
3-7	0	1.6M Belt	1		2-14	······································	5015 Air blower fixed plate	1	
3-8	LO COLLE	1.5M USB wire	1		2-15		Z axis motor fixed plate	2	
3-9		Four parts below in this bag	1		2-16		Support plate lock plate	2	

Item	Picture	Name	QTY	Check	Item	Picture	Name	QTY	Check
3-9-1		4.5M Winding pipe	1		2-17		Y axis motor fixed plate	1	
3-9-2		Belting	10		2-18	***	Y axis belt bearing support	1	
3-9-3		R clip	3		2-19		Wind mouth	1	
3-9-4	XX	Locating piece	2		2-20		1.5M Power line	1	
3-10	Ш	Power Supply	4		2-21		16GB TF card and card reader	1	
3-11		Power Supply	1		2-22		X Motor line 40CM Y Motor line 40CM Left Z Motor line 40CM Right Z Motor line 90CM Extruder Motor line 90CM	5	