











Battery Input



Battery to 5V LDO



Current Sensing



Low pass filter because there may be noise from being underneath buzzers

$$f_c = 1/(2\pi \cdot R \cdot C)$$

$$= 1/(2\pi \cdot 10kR \cdot 0.39uF)$$

$$= -40.8 \text{ Hz}$$
