

Reset + Bootloader Buttons


SW\_Push

BOOT

SW\_Push

R9 10k

10k RESET



MOTORB\_OUT2

→ DRV8837

C15 12pF

VDD3P3\_CPU\_\_45 VDD\_SPI

> VDD3P3 VDDA

VDD3P3\_RTC\_IO

VDD3P3\_RTC

DRIVERB SLEEP

MOTORB\_IN1 GND MOTORB\_IN1