


ITEM NO.	PART NUMBER	QTY.
1	M3 x 12mm Socket Head Screw	1
2	XY Stepper Mount Mirror_0.01	1
3	XY Stepper Mount_0.01	1
4	Y axis 8mm Shaft Clamp Mirror_0.01	1
5	Y Axis 8mm Clamp Small_0.01	1
6	Y Axis 8mm Shaft Clamp_0.01	1
7	Y Axis M3 8mm Shaft Mount_0.01	1
8	GT2 20T Fixed Pulley_0.01	2
9	IGUS 8mm Bearing_0.01	2
10	IGUS 8mm precision rod 400mm_0.01	2
11	nema17_0.01	2
12	M3 Post Fit T Slot Nut_0.01	3
13	M3 x 16mm Socket Head Screw	3
14	M3 Nut	4
15	ISO 7380 - M5 x 10 - 10N	10
16	M3 x 10mm Socket Head Screw	10











DETAIL B SCALE 1:2



DETAIL C SCALE 2:5



DETAIL D SCALE 2:5

REVISION	1	DRAWN BY	A Meadows
DATE	01/03/2017	ENGINEER	AMEADOWS

CHANGE NOTES

ES GENERAL NOTES

REMOVE ALL SHARP EDGES AND BURRS

PARTS TO BE CLEAN AND FREE FROM OIL AND GREASE

THE USER OF THIS DRAWING IS RESPONSIBLE FOR ENSURING THEY HAVE THE LATEST ISSUE

DO NOT SCALE. WORK TO DIMENSIONS ONLY

DIMENSIONS IN MILLIMETRES

ED I	TOLERANCE HEIRARCHY IN DESCENDING ORDER		0-250mm	250-1000mm	1000+mm
, i	MACHINING		±0.1mm	±0.2mm	±0.5mm
	HOLE SIZE		+0.3 - 0 mm	+ <sup>0.5</sup> mm	+ <sup>0.5</sup> mm
KA FERWIS	HOLE POSITION		±0.3mm	±0.5mm	±0.5mm
<b>∸</b>	FORM/PROFIL	.E	±0.5mm	±1.0mm	±1.0mm
	ASSEMBLIES/FABRICATIONS		±0.5mm	±1.0mm	±2.0mm
<u> </u>	ANGLES		±0.3°	±0.1°	±0.1°
	C17E	SEE CONADONIENT DADTS			

A L	SIZE	SEE COMPONEN	E COMPONENT PARTS	
MATERIAI	MATERIAL	SEE COMPONENT PARTS		
ATE	SPEC	SEE COMPONENT PARTS		
Σ	FINISH	None		
DRAWING SCALE		1:5	· ·	
DRAWING SI7E		A3		

А3

TITLE: Y Axis Assembly\_0.01

STATUS: Released

0.34Kg

DRAWING SIZE

SHEET 1 OF 1