

**ERASMUS+  
GEMS  
DIAMOND**




# DC Motor Drives

Hardware overview and system architecture

Dr. Sachin Yadav






# Lecture Outline

- 1 DC drive system introduction
- 2 Hardware architecture
- 3 Feedback and sensing
- 4 Close-loop control

**What is the system  
architecture of a DC  
drive system?**

# DC drive system overview



**Power converter:** power electronics, gate drivers etc. to enable a DC-DC conversion

**DC bus voltage sensor:** measure DC bus voltage to calculate duty cycle or for protection



**Armature current sensor:** measure armature current for feedback control

**Rotor position sensor:** measure the rotor speed and position for speed or position tracking

**Control hardware:** micro-controller (MCU), digital signal processor (DSP) or field-programmable gate array (FPGA) based hardware with pulse width modulation (PWM), analogue-digital conversion (ADC) and digital encoder/resolver interfaces etc.

**How to sense the  
voltage, current and  
rotor position?**

# Voltage sensing hardware




- **Voltage divider** with large resistance to turn high voltage to small signal;
- **Isolation amplifier** to isolate low voltage control circuit to high voltage power circuit.


Source: Texas Instruments,  
[https://www.ti.com/lit/ds/symlink/amc1311.pdf  
?ts=1755430089672](https://www.ti.com/lit/ds/symlink/amc1311.pdf?ts=1755430089672)

# Current sensing hardware

## Shunt resistor sensing






## Hall effect based sensor



- Measure current via voltage drop across a small but precise in-line resistor
- Isolation amplifier needed
- Additional loss
- Immunity to magnetic interference
- High accuracy, small size

- Measure current based on hall effect:  $v_H$  proportional to magnetic field caused by current
- Vulnerable to magnetic interference
- Expensive for high accuracy
- No physical contact with main circuit: no isolation amplifier needed
- NO power dissipation

# Rotor position sensing: quadrature encoder



- Incremental counting at every rising/falling edge
- Index signal needed to know the absolute position (homing)



# Rotor position sensing: advanced solutions

## Variable reluctance resolver



- Three coils on teeth
  - Sin and Cos
  - Excitation

Source: Tamagawa Seiki




## Magnetoresistive (MR) sensor



Source: Continental

- MR effect
  - Magnetic field controller resistance
  - Sine and cosine output




## Other types of position sensors

- Brushless resolver (excitation by rotational transformer)
- Inductive position sensor
- Hall effect sensor

# How to measure rotor speed from position sensors?

---

# Measure speed from rotor positions



First order approximation

$$v = \frac{d\text{pos}}{dt} \approx \frac{\Delta\text{pos}}{\Delta t}$$

Change in position

Change in time



- Fixed time increment (M method)
  - $\Delta\text{pos}$  updated at fixed  $\Delta t$
  - Speed resolution  $1/\Delta t$
  - Suitable for moderate to high speed
- Fixed change in position (T method)
  - $\Delta t$  measured between a specific  $\Delta\text{pos}$
  - Resolution based on speed
  - Zero speed not detectable
  - Suitable for low speed

# Measure speed from rotor positions: tracking loop

- Problems first-order approximation

- Time delay, limited bandwidth
- None zero steady state error
- Prone to noise

- Advanced solution: a tracking loop




- Proportional-integral (PI) control loop or a Luenburger observer drives position estimation steady state error to 0.
- Integrate the estimated velocity to get the position.
- Optimal than M or T method for noise rejection and bandwidth.


# How to realize feedback control based on hardware components?

# Feedback control of DC motor drive


- Use sensor readings to approach reference values
  - Close-loop current control



- Cascaded close-loop speed control




- Cascaded close-loop position control



# Conclusions

- DC motor drive consists hardware components: power converter, voltage/current sensors, position sensors and controller.
- Quadrature encoder measures incremental position change. Absolute position is measurable if a homing reference is used.
- A tracking loop can be used to estimate speed from position sensors.
- Various close loop controls are possible with feedback from sensors.



# Thank you for watching!

This video was created by Delft University of Technology for the GEMS Erasmus+ project (a collaboration between University of Ljubljana, University of Alcala, Teaching Factory Competence Center, and Delft University of Technology). It is released under a [Creative Commons Attribution Non Commercial Share Alike 4.0 International License](#)



**Co-funded by  
the European Union**

Views and opinions expressed are however those of the author(s) only and do not necessarily reflect those of the European Union or CMEPIUS. Neither the European Union nor the granting authority can be held responsible for them.