

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD
CENTRAL VALLEY REGION

ORDER NO. 75-235

WASTE DISCHARGE REQUIREMENTS
FOR
KERN COUNTY SERVICE AREA NUMBER 40
(PINE MOUNTAIN CLUB)
Kern County

The California Regional Water Quality Control Board, Central Valley Region (hereinafter Board), finds:

1. Pine Mountain Club, Incorporated, a subsidiary of Tenneco West, is the developer of Pine Mountain Club Subdivision in the Mill Potrero area, twelve miles west of Frazier Park, T9N, R21W, and R22W, SEB&M, Kern County.
2. Pine Mountain Club Subdivision encompasses 3,002 acres with 3,000 residential units on about 1,000 acres, eleven acres for commercial use, a golf course, equestrian center, and overnight camping.
3. Waste discharges within the Subdivision are presently governed by Order No. 72-148, adopted 23 January 1972. These requirements are not current or adequate.
4. Kern County Service Area No. 40 (hereinafter discharger) has been formed to manage and control disposal of wastes and is empowered to plan, design, finance, construct, operate, maintain and to abandon, if necessary, any sewerage system or the expansion of any sewerage system and sewage treatment facilities serving the area and Pine Mountain Club. In addition, the Service Area will have supervision over the location, design, construction, operation, maintenance and abandonment of individual sewage disposal systems within the area and Pine Mountain Club, and is empowered to design, finance, construct, operate and maintain any facilities necessary for the disposal of wastes pumped from individual sewage disposal systems and will conduct any monitoring or surveillance programs required for water quality control purposes.
5. Sewage disposal, initially, is to be by individual subsurface systems.
6. Available data indicate that topography, thin soil mantle, low soil permeability, depths to groundwater and generally unfavorable conditions in some areas of the development will present major difficulties with disposal of sewage by individual septic tank-leach field systems or seepage pits under full development and construction of collection systems and treatment facilities may be necessary.
7. The Board adopted a Water Quality Control Plan for the Tulare Lake Subbasin on 25 July 1975.
8. The Board has notified the discharger and interested agencies and persons of its intent to prescribe waste discharge requirements for the discharge and has provided them with an opportunity to submit their written views and comments.

9. The Board in a public meeting has heard and considered comments pertaining to the discharge.

IT IS HEREBY ORDERED, the Discharger shall comply with the following:

A. Waste Discharge Specifications

1. Neither the treatment nor discharge of waste shall cause a nuisance or pollution as defined in the California Water Code.
2. There shall be no direct discharge from individual domestic sewage disposal systems to waters of the State.
3. Effluent from individual disposal systems shall be maintained underground at all times. Where land slopes in the disposal area exceed 20 percent (20 feet vertical rise in 100 feet horizontal) the total treatment and disposal system must be engineered and designed to keep effluent underground.
4. The discharge from each subdrain system shall not exceed a mean of 200 fecal coliform bacteria per 100 ml or an instantaneous maximum of 500 fecal coliform bacteria per 100 ml.

B. Prohibitions

1. The discharge of wastes from individual domestic sewage disposal systems in the Pine Mountain Club Subdivision is prohibited in locations where one or more of the following conditions exist.
 - A. Soil depths below the invert of leach lines or bottom of seepage pits to an impervious strata is less than ten feet.
 - B. Depths to groundwater below the invert of leach lines or the bottom of seepage pits is less than five feet.
 - C. Standard percolation tests on the disposal area show rates greater than 60 minutes per inch.
 - D. Leach lines or seepage pits are located less than 100 feet from the "thread of any stream" (center line) as determined by a field measurement, or as shown on the 1" = 80' scale contour maps described in Section XII, D (Page 13) of the manual, "Regulatory Procedures for County Service Area No. 40 (Pine Mountain Club), County of Kern, June 1973."
 - E. Leach lines or seepage pits are located less than 25 feet from subdrains installed to lower groundwater levels, or as shown on the 1" = 80" scale contour maps described in Section XII, D (Page 13) of the manual, "Regulatory Procedures for County Service Area No. 40 (Pine Mountain Club), County of Kern, June 1973."

F. Leach lines or seepage pits are located less than 100 feet from the high water line of any lake or impoundment or from any public or private water well.

C. Provisions

1. Order No. 72-148 is hereby rescinded.
2. Waste discharges from individual domestic sewage disposal systems shall be monitored in accordance with the Monitoring and Reporting Program No. 75-235 and the General Provisions for Monitoring and Reporting as specified by the Executive Officer.
3. The developer shall require as a condition of sale that domestic sewage disposal systems on individual lots are subject to the obtaining of a permit through the County Service Area and to the supervision by the County Service Area over the location, design, construction, operation, maintenance, monitoring and abandonment, if necessary, of such systems.
4. The developer shall include in the recorded tract restrictions and the public report for any new tracts recorded subsequent to 28 January 1972, the conditions under which the discharge of wastes from individual domestic sewage disposal systems will be prohibited.
5. This Order does not constitute a license or permit; neither does it authorize the commission of any act resulting in injury to the property of another, nor does it protect the discharger from his liabilities under federal, state, or local laws.
6. The Board will review this Order periodically and may revise the requirements when necessary.

I, JAMES A. ROBERTSON, Executive Officer, do hereby certify the foregoing is a full, true, and correct copy of an Order adopted by the California Regional Water Quality Control Board, Central Valley Region, on OCT 24 1975

Original signed by
James A. Robertson

JAMES A. ROBERTSON, Executive Officer

08/08/75 LSO/ic

CALIFORNIA REGIONAL WATER QUALITY CONTROL BOARD
CENTRAL VALLEY REGION

MONITORING AND REPORTING PROGRAM NO. 75-235

FOR
KERN COUNTY SERVICE AREA NUMBER 40
(PINE MOUNTAIN CLUB)
Kern County

SUBDRAIN MONITORING

Samples shall be collected at the discharge point of each subdrain system. The Kern County Service Area will provide appropriate information to locate and define all sampling points.

<u>Constituent</u>	<u>Units</u>	<u>Type of Sample</u>	<u>Frequency</u>
Fecal Coliform	MPN/100 ml	3 replicate	Quarterly

GROUND WATER MONITORING

Samples shall be collected from all water supply wells operated by Mill Potrero Water Company. Samples shall be collected prior to any treatment or distribution of the water.

<u>Constituent</u>	<u>Units</u>	<u>Type of Sample</u>	<u>Frequency</u>
Electrical Conductivity	micromhos	Grab	2/year
pH	pH units	Grab	2/year
Total Coliform	MPN/100 ml	3 replicate	Quarterly

SURFACE WATER MONITORING

<u>Constituent</u>	<u>Units</u>	<u>Type of Sample</u>	<u>Frequency</u>
Total Coliform	MPN/100 ml	3 replicate	Quarterly
Fecal Coliform	MPN/100 ml	3 replicate	Quarterly

REPORTING

Reports of the analytical results shall be provided by the Kern County Service Area.

Annual reports shall include the number of new installations, number of system failures, a description of cause and effect of such failure, description of remedy applied to failure, and a description of the state of the system.

MONITORING AND REPORTING PROGRAM
KERN COUNTY SERVICE AREA NUMBER 40
(PINE MOUNTAIN CLUB)
Kern County

- 2 -

In reporting the monitoring data, the discharger shall arrange the data in tabular form so that the date, the constituents and the concentrations are readily discernible. The data shall be summarized in such a manner to illustrate clearly the compliance with waste discharge requirements.

Monitoring reports shall be submitted to the Regional Board by the 15th day of the month following due date.

Ordered by:

JAMES A. ROBERTSON, Executive Officer

(date)

ISO/ic 08/11/75

KERN COUNTY SERVICE AREA NUMBER 40
(PINE MOUNTAIN CLUB)
Kern County

Pine Mountain Club, Incorporated a subsidiary of Tenneco West, has developed a subdivision in the Mill Potrero area, about 12 miles west of Frazier Park at an elevation of 5,000 feet and above. The subdivision is located at an inter-mountain valley trending in an East-West direction, and is within the Los Padres National Forest.

Waste Discharge Requirements, Order No. 742-148, adopted 28 January 1972 presently governs waste discharges within the development. Order No. 72-148 is no longer adequate.

The development is composed of six tracts encompassing a gross area of about 3,000 acres. The plan of development consists of about 3,000 residential units on about 1,000 acres. The average lot size in the development is about 0.35 acres. The minimum lot size is 10,000 square feet. In addition, eleven acres have been proposed for commercial development consisting of a grocery store and laundromat and possibly a restaurant, motel and service station. A golf course, equestrian area and overnight camping area are also included in the development plan. With the exception of a narrow canyon located downstream of the development, Pine Mountain Club is surrounded by Los Padres National Forest. Source of the water supply is groundwater supplied by Mill Potrero Mutual Water Company. Treatment facilities for the removal of iron and manganese have been installed.

The method of sewage disposal is by individual subsurface systems. Percolation and soil tests conducted throughout the subdivision indicate that areas with unfavorable disposal conditions exist. Septic tank leach systems will be constructed in those areas approved by the county and seepage pits will be used in areas where slopes are too steep or percolation rates are unsatisfactory.

Geologic reports submitted by the developer indicate that the area is dominated by the San Andreas Fault Zone. Movement along this fault has changed the land forms and caused variation of water table elevation. There are three areas with extremely high water tables; namely, the Lower Meadow Basin, the Meadow Basin, and a small marshy area located about one-half mile south of the commercial area. The two lower areas are being modified by installation of subdrains. Areas with high water table will be maintained as open area, golf course, or will remain undeveloped until a sewage collection system is installed.

The location of the entire subdivision was based on avoiding those areas that showed active movement along the San Andreas Fault at the time of the 1857 Tejon Earthquake. All of the proposed building area is south of the San Andreas Fault Zone.

Revised waste discharge requirements have been formulated to prevent nuisance and pollution.