Sheet1

r0 r1 r2	a1 a2 a3	1° arg y salida 2° arg y salida	caller save Instrucciones de 4 bytes Thumb => inst. De 16 bits	
r3	as a4	3° arg 4° arg	Thumb => list. De 10 bits	
		•		
r4	V1	variables	callee save	
r5	v2			
r6	v3			
r7	v4			
r8	v5			
r9	v6	Especial, cuidado		
r10	v7			
r11	v8			
r12		IP	Para saltos largos	
r13		SP		
r14		LR	Link Register, return address	
r15		PC	Program counter	

s0 a s15 s16 a s31	argumento	os y retorno de punto flotante	caller save	
CPSR Bits:	(Current Program Status Register) V Overflow		S0:S1 s2:s3	d0 d1
	C	Carry		
	Z	Zero	s30:s31	d15
	N	Negative		

Sheet1

[rn] (%rn)
bl destino Branch and link [rn,rm] (%rn,%rm,1)
[rn,#i] i(%rn)