SYNTHETIC SAMPLE — all parties are fictional, for GlobalInfra AI demonstration only

Global Rail Contractor (Demo) Sdn Bhd – Quality Department

Kuala Lumpur, Malaysia

NON-CONFORMANCE REPORT NCR-2026-084

Subject: Concrete Crack at Pier P52 Column, Station S13 Viaduct

Project: MY-RAIL-A Kuala Lumpur Corridor Rail Project, Package 2, Malaysia

Issued by: Quality Department, Global Rail Contractor (Demo) Sdn Bhd

Date: 10 October 2026

Location: Pier P52 column, Station S13 viaduct, Kuala Lumpur, Malaysia

Description: During inspection, a vertical concrete crack was found on the north face of the P52 column, about 1.2 m long with a maximum width of 0.4 mm. Minor honeycomb
was also observed near the construction joint.

Required action: record crack location, width and chronology; investigate the cause before assigning responsibility; propose corrective action within 7 days.

Raised by: Lim Mei Ling (fictional), QA/QC Engineer

合成示例资料：单位与人员均为虚构，仅用于 GlobalInfra AI 演示