# 0809 实验


# 一、实验内容

将 INTO—INT7 分别连接到 2 个可变电阻器上,每秒采集一次 0809 转换的数字量, 要求:

- 1、将转换后的数字量和路号在 CRT 上显示,同时将将转换后的数字量送往 8 段显示器显示,采集 10 个循环后结束。
- 2、将采集到的数据送往内存 TABLE 开始的 240 个单元中存放。

# 二、0809知识

1. ADC0809 的工作过程:



第一步: 首先确定 ADDA、ADDB、ADDC 三位地址,决定选择哪一路模拟信号。 第二步: 使 ALE 端接收一正脉冲信号,使该路模拟信号经选择开关达到比较器 的输入端。

第三步: 使 START 端接收一正脉冲信号,START 的上升沿将逐次逼近寄存器复位,下降沿启动 A/D 转换。

第四步: EOC 输出信号变低,指示转换正在进行。


第五步: A/D 转换结束, EOC 变为高电平, 指示 A/D 转换结束。此时, 数据已保存到 8 位锁存器中。

第六步: OE 信号变为高电平,则 8 位三态锁存缓冲器的三态门被打开,转换好

的 8 位数字量数据被输出到数据线上。

如上所述,EOC 信号变为高电平表示 A/D 转换完成,EOC 可作为中断申请信号,通知 8086CPU 取走数据。在查询传送方式中,EOC 可以作为 8086 查询外设的状态信号

#### 2. 实验电路图



#### 三、参考程序

;PC7--0809 的 EOC;PC0--8253 的 out1;PA--7 段数码管: PB4--数码管的 S0: PB5--数码管的 S1

## DATA SEGMENT

TABLE\_LED DB 3FH,06H,5BH,4FH,66H,6DH,7DH,07H
DB 7FH,6FH,77H,7CH,58H,5CH,79H,71H
DB 80H

TABLE\_CRT DB 30H,31H,32H,33H,34H,35H,36H,37H DB 38H,39H,41H,42H,43H,44H,45H,46H

TABLE\_KONG DW 0,290H,291H,292H,293H,294H,295H,296H,297H

NUM1 DB 10H

NUM2 DW 1010H

TABLE\_CUN DB 240 DUP(0)

### DATA ENDS

```
STACK1 SEGMENT PARA STACK
      DW 40H DUP(0)
STACK1 ENDS
CODE SEGMENT
     ASSUME CS: CODE, DS:DATA, SS:STACK1
START:
     MOV AX, DATA
     MOV DS, AX
     CALL Init_8253; 地址: 288-28BH,初始化 8253, 使之产生 1s 方波
     CALL Init_8255; 地址: 280-283H,初始化 8255, A 口输出, B 输出, C 口高位输入, C 低入
     CALL WAIT_INSPACE;
     MOV CX, 11
     MOV SI, 0
INIT:
     MOV DI, 0
READ_INPUT:
     CALL LIGHT_LED ;8 段显示
     MOV DX,282H ;读C口
     IN AL, DX
     AND AL, 01H ;PC0=0?
           READ_INPUT ; PCO=0
     JZ
     INC DI
     CMP DI, 9
     JZ NEXT_INPUT
     PUSH DI
     SHL DI, 1
     MOV DX, TABLE_KONG[DI]
     POP DI
     OUT DX, AL
     CALL DELAY
     IN AL, DX
     MOV AH, AL ; 高位 AH 低位 AL 中
     PUSH CX
```

```
MOV CL,4 ;读高 4 位 AH 中
     SHR AH,CL ;读高 4 位 AH 中
     POP CX
     AND AL, OFH;低位 AL 中
     MOV NUM2, AX
     MOV AX, DI
     MOV NUM1, AL
     CALL CRT; CRT 显示
     CALL SAVE2BUF
WAIT_TIMEOUT:
     MOV DX, 282H;读 C 口
     IN AL, DX
     AND AL, 01H
     JNZ WAIT_TIMEOUT ;PC0=1
     JMP READ_INPUT
NEXT_INPUT:
     DEC CX
     CMP CX, 0
     JZ FINAL ;CX=0?
     JMP INIT
FINAL:
    MOV AH, 4CH
    INT 21H
DELAY PROC NEAR
     PUSH DX
  AGAIN:
     MOV DX, 282H;读 C 口
     IN AL, DX
     AND AL, 80H; PC7=0?
     JZ AGAIN ;PC7=0
     POP DX
     RET
DELAY ENDP
```

LIGHT\_LED PROC NEAR

MOV AL, OH;熄灭

MOV DX, 281H

OUT DX, AL

MOV AX, NUM2

LEA BX, TABLE\_LED;取低位

XLAT TABLE\_LED

MOV DX, 280H

OUT DX, AL

MOV AL, 10H;PB4=1, 点亮

MOV DX, 281H;

OUT DX, AL

MOV AL, 0H;熄灭

MOV DX, 281H

OUT DX,AL

MOV AX, NUM2

MOV AL, AH

XLAT TABLE\_LED;取高位

MOV DX, 280H

OUT DX, AL

MOV AL, 20H;送 PB5=1,点亮

MOV DX, 281H

OUT DX, AL

MOV AL, 0H;熄灭

MOV DX, 281H

OUT DX, AL

RET

LIGHT\_LED ENDP

CRT PROC NEAR

```
MOV AL, NUM1
     LEA BX, TABLE_CRT
     XLAT TABLE_CRT;取低位
     MOV DL,AL
     MOV AH, 02H
     INT 21H
     MOV DL,"
     MOV AH, 02H
     INT 21H
     MOV AX, NUM2
     MOV AL, AH
     LEA BX, TABLE_CRT;取高位
     XLAT TABLE_CRT
     MOV DL, AL
     MOV AH, 02H
     INT 21H
     MOV AX, NUM2
     XLAT TABLE_CRT;取低位
     MOV DL, AL
     MOV AH, 02H
     INT 21H
     MOV DL."
     MOV AH, 02H
     INT 21H
     MOV DL, ''
     MOV AH, 02H
     INT 21H
     RET
CRT ENDP
SAVE2BUF PROC NEAR
      MOV AL, NUM1
      MOV TABLE_CUN[SI], AL
      INC SI
      MOV AX, NUM2
      MOV TABLE_CUN[SI], AH
```

```
INC SI
       MOV TABLE_CUN[SI], AL
      INC SI
      RET
SAVE2BUF ENDP
Init_8253 PROC;
      MOV DX, 28BH ;8253 控制字
      MOV AL, 00100101B
      OUT DX, AL
      MOV DX, 288H
      MOV AL, 10H
      OUT DX, AL
      MOV DX, 28BH
      MOV AL, 01100111B
      OUT DX, AL
      MOV DX, 289H
      MOV AL, 10H
      OUT DX, AL
      RET
Init_8253 ENDP
Init_8255 PROC
     MOV AL, 10001001B;控制字 A 出, B 出, C 高入, C 低入
     MOV DX, 283H
     OUT DX, AL
     RET
Init_8255 ENDP
WAIT_INSPACE PROC
  NEXT:
     MOV AH, 01H
     INT 21H
     CMP AL, 20H
     JNZ NEXT
     RET
WAIT_INSPACE ENDP
```

CODE ENDS END START