

rain P_j + irrigation I_j
evaporation & losses
$(1-\alpha_P)P_j + (1-\eta_w)I_j$
overflow Q_j
(lost)
effective inflow
$\alpha_P P_j + \eta_w I_j$
capacity C
plant transpiration
(root uptake only)
$T_{a,j} = \min(M_j,\ K_s D_j)$
no stress
$K_s = 1$
threshold $(1-p)C$
stressed
$K_s = \dfrac{M_j}{(1-p)C}$
store M_j
carried to the next day and the next year